



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear door RH / <i>DD</i>		1210.00 /	
1	Rear door protector film RH / <i>APC</i>		45.00 /	
1	Rear door lower garnish RH / <i>MIS</i>		145.00 /	
1	Rear fender lower garnish RH / <i>CNT</i>		95.00 /	
1	Rear fender RH (Repair refer to labour) <i>X R</i>		0.00	
1	Rear bumper (Repair refer to labour) <i>X RH</i>		0.00	
1	Rear rim 17 inch (Repair refer to labour) <i>X R</i>		0.00	
Part Items Total:			1495.00	1495
			-20%	-299
			1196.00	1196
<u>SPECIAL NETT ITEMS</u>				
1	Side skirt step up rails assy RH / <i>CNT</i>		680.00	500 /
1	Rear Tyre RH 225/60R17 / <i>TN (80% of \$250)</i>		280.00	200 /
SN Items Total:			960.00	
Total Parts			2156.00	700



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400
3	To perform anti-rust treatment on affected areas	60.00	30
4	Check and wheel computerize alignment	80.00	60
5	To remove and refix front tyre and wheel balancing in order to rear rim LH	50.00	30
	1090		
	Labour Total :	1790.00	
	TOTAL (PARTS & LABOUR):	3946.00	

P- 1196
 M- 700
 L- 1020
 Supp - 906
 3822

L/S - 3057.60
 = 3050

Steve (LKK)
 24/8/21, 11.00am

WHL RL
 L/S
 My RL Sy
 5 days