



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008848/Euf3e2	
			Date: 02/09/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4509M	Veh. Inspected	SLM 9598Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/21/2049	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	24/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI TUCSON	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KMHJ3812VJU465966	Colour	BLACK
	Odometer	71182 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R17	YOKOHAMA	5 mm
	L/H Front Tyre	225/60 R17	YOKOHAMA	5 mm
	R/H Rear Tyre	225/60 R17	YOKOHAMA	5 mm
	L/H Rear Tyre	225/60 R17	YOKOHAMA	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/08/2021	Inspection Date	24/08/2021
	Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	