


ASS. REC. BY: Steve T. REPT CS/SMR 21008848/Euf3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD: TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SLM 9598Y
at Workshop m/s WAH HONG MOTORS
at _____
Insured: SHC4509M
Policy No. _____
Claims No. TAX/08/21/2049
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: Consistent? : Yes or No
SIA / PR Seen: Consistent? : Yes or No
Est. Repair: 5 days Res.: Yes or No
Cum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN/OUT

Veh No: SLM 9598Y Yr Regn: 19/4/17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai Tucson c.c. 1591
Colour: Black A/C: Insured / Std / NI / N
Sp. Reading: 7482 T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: KMH13812:VM465966
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Locked / Burnt or
Brake: In order / Jammed / Locked / Burnt or
Mod: NII / S/Rim / STD A/Rim or
Tyre Size: F: 225/60R17 R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: 5 mm R/Bal: 5 mm
L/Bal: 5 mm L/Bal: 5 mm
D.O.A. 22/8/21 O.O.L. 24/8/21
Survey held at Wah Hong
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear RH: _____
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	AKK- / SK
Confirmed final fig L/S \$3050, 5 repair days.	
(RED \$2261, 43%)	

Time/Time, File, Ross 107. ☐ : Procl. Report
1/9 TYPIST ☐ : Final Report

Time/Time, File, Ross 107.
TP
\$3050

Days Of Repair: 5
Resurvey No. of Trips: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation	
\$ + RS + SI	
Private	
Others	
TOTAL	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>		Part Items Total:	1210.00			
1	Rear door RH — <i>OD</i>		45.00			
1	Rear door protector film RH — <i>pec</i>		145.00			
1	Rear door lower garnish RH — <i>MIS</i>		95.00			
1	Rear fender lower garnish RH — <i>cut</i>		0.00			
1	Rear fender RH (Repair refer to labour) <i>X R</i>		0.00			
1	Rear bumper (Repair refer to labour) <i>X nn</i>		0.00			
1	Rear rim 17 inch (Repair refer to labour) <i>X R</i>		0.00			
			-20%	1495.00		
				-299.00		
				1196.00		
<u>SPECIAL NETT ITEMS</u>						
1	Side skirt step up rails assy RH — <i>cut</i>		680.00			
1	Rear Tyre RH 225/60R17 — <i>TN (80% of \$250)</i>		280.00			
		SN Items Total:	960.00			
		Total Parts	2156.00			



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400
3	To perform anti-rust treatment on affected areas	60.00	30
4	Check and wheel computerize alignment	80.00	60
5	To remove and refix front tyre and wheel balancing in order to rear rim LH	50.00	30
Labour Total :		1790.00	
TOTAL (PARTS & LABOUR):		3946.00	

Steve (LKK)
24/8/21, 11:30am

WHL RL
L/S
My AC Sy
5 dgs

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/08/2021 14:22 (SGT)
Date of Accident	22/08/2021 08:50 (SGT)
Exact Location of Accident	Near 1A Holland Grove Dr, Singapore 278849
Additional Location Information	T-JUNCTION OF MOUNT SINAI DR & HOLLAND GROVE DR
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM9598Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	HU IVAN
NRIC No	SXXXX415B
Email Address	HUIVAN29@GMAIL.COM
Mobile Phone No	(Phone) +65-81989007
Alternative Phone No	+65-81989007

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Tucson
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00452405/03
Cover Note Number	-

DRIVER

Name of Driver	HU IVAN
NRIC No	SXXXX415B

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	KOH THONG JOO
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Declaration

Policyholder's Signature / Date &
Time

Witnessed by Reporting Centre
Personnel



Annex D

NOTICE OF REPORTING

This is to confirm that Hu Ivan, NRIC: S8039415B, Contact: 81989007, has reported to the Police a Non Injury traffic accident which occurred along Mt Sinai Rd(major road) diagonal to Holland Grove Drive(minor road).

On the 22/08/2021 at about 0850hrs, I was driving my vehicle bearing the registration plate number SLM9598Y, Hyundai Tucson, I was driving along Mt Sinai Rd when suddenly a SMRT taxi bearing registration plate number, SHC4509M, rushed out from Holland Grove Drive and hit the rear right of my vehicle. My vehicle suffered a damaged tire and dents on the rear right passenger door, the other vehicle suffered significant damage on the front left bumper.

We both then exited our vehicles and we exchanged our particulars for insurance claim. The other party is one namely, Koh Thong Joo NRIC: S7136088A. I had my 7-year old son sitting at the rear and both of us are not injured, the other party was not injured as well.

I am lodging this for insurance purposes.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SC/Sgt Sean Siva

Date: 22/08/2021

Time: 0850hrs

S/D Ref: 51

Police Post/Unit: Clementi Neighborhood Police Centre



Clementi NPC
Clementi Division
20 Clementi Ave 5 S(129858)
Tel: 1800 - 8729999