



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear lower arm rh - BT		335.00	- 360 -
1	Rear knuckle arm rh - BT		185.00	250 -
1	Rear wheel hub with bearing rh - Jammed		345.00	
				945
				-20%
				756
			#REF!	
			#REF!	
SPECIAL NETT ITEMS				
LABOUR				
1	To remove and replace rear undercarriage RH		200.00	150 -
				906
Total Parts			#REF!	