



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMC5900A TOYOTA WISH 1.8

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Boot lid / DD		1719.00	1280 ✓
1	Boot lid lock / BT		590.00	389 ✓
2	Boot lid damper LH/RH @2*\$371 X AN		742.00	
1	Boot lid logo badge / APC		62.00	✓
1	Boot lid "aero tourer" / APC		70.00	✓
1	Boot lid "Borneo motor" / APC		58.00	✓
1	Rear bumper / DD		481.00	✓
2	Rear bumper side retainer LH/RH @2*\$191 75 - BR		382.00	150 ✓
✓	Tail lamp lower bracket LH/RH @2*\$181 60 (RH) - BR		362.00	60 ✓
✓	Rear bumper side reflector LH/RH @2*\$191 70 (RH) - (4T)		382.00	70 ✓
2	Rear reinforcement side beam LH/RH @2*\$122 80 ? - BT		244.00	160 ✓
1	End panel / DD (photo)		571.00	✓
1	End panel top garnish ? - CR4		371.00	245 ✓
1	Exhaust muffler (chrome cover) - BT		780.00	231 ✓
1	Front bumper / CR4		481.00	✓
2	Front bumper side retainer LH/RH @2*\$172 X BR Repeated		342.00	
2	Headlamp LH/RH @2*\$1219 862 - (4T) / BR		2438.00	1724 ✓
1	Support panel (Repair refer to labour) X AN		0.00	
			10075.00	
			-25% -2518.75	
			7556.25	
SPECIAL NETT ITEMS				
1	Windscreen moulding (rear) - APC		180.00	170 ✓
1	Front bumper clips / APC		35.00	30 ✓
1	Front center grille clips X AN		30.00	
1	Front car plate with holder / BR		35.00	✓
1	Rear reverse sensor / BR		200.00	✓
1	Rear windscreen sealant / APC		50.00	40 ✓
1	End panel sealant / APC		50.00	30 ✓
1	Rear bumper clips / APC		35.00	30 ✓
Total Parts			8171.25	

6032
-25%
4524

485



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMC5900A TOYOTA WISH 1.8

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	/
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove, replace and focus both headlamp beam	60.00	30
6	To remove and replace rear reverse sensor	60.00	30
7	To remove and replace exhaust muffler	150.00	1 30
8	To remove and refix rear windscreen	150.00	120
Labour Total :		2380.00	
TOTAL (PARTS & LABOUR):		10551.25	

Steve (LKK)

24/8/21, 11.00am

WHL PL = 7379

L/S

L/S-5903-20

My AL sy

= 5900

7 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: