



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 04/10/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ZVW40R	AWXEBW Q3	15/01/2020	SMR5871X	0	64021	73/DS/SMR5871X
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU20J055557		2ZR2G43254	60	Ary Chua	07/09/2021 8.00		04/10/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE:11/08/2021 17:34 ACC DATE:11/08/2021 09:10 TP VEH:SHB5717C DRIVE IN:11/08/2021 16:48 DATE SURVEY:07/09/2021@10.10 STEVE CHEN(LKKAUTO) NO OF REPAIR DAYS: 3 DAYS				30.00	
2	B	BP-LAB2 TO CHECK WIRING AND LIGHTING.	BP03			122.40	
3	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.	BP03			180.00	
4	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	BP03			720.00	
5	B	BP-RES2 SPRAY PAINT RR.BUMPER ONLY(1P)	*			590.00	
6	1	T52159-47912 COVER, RR BUMPER	1.00	561.50		561.50	
7	2	K52161-0K040 PIECE, RR BUMPER	12.00	4.10		49.20	
8	3	U52575-47030 RETAINER, RR BUMPER	1.00	59.70		59.70	
9	4	U52576-47030 RETAINER, RR BUMPER	1.00	59.70		59.70	
10	5	U76891-47040 SPOILER, RR NO.1	1.00	856.90		856.90	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 3,229.40
					Parts 1,587.00		GST 7.00% 226.06
					Labour 1,642.40		
					Sublet 0.00		
					Lubrication/Fluid 0.00		
					Others 0.00		
					Less 0.00		Amount Due 3,455.46

Customer Copy