



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008857/Euf3e2	
			Date: 07/10/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 5717C	Veh. Inspected	SMR 5871X	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/21/2021	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	24/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS PLUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDZS3EU20J055557	Colour	GREY	
Odometer	114343 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	DUNLOP	4 mm	
L/H Front Tyre	205/60 R16	DUNLOP	4 mm	
R/H Rear Tyre	205/60 R16	DUNLOP	4 mm	
L/H Rear Tyre	205/60 R16	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2021	Inspection Date	07/09/2021	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	