

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008858/GQC�2**Date:** 16/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00106982101
Claimant Vehicle No :	SMJ725K	Insured Vehicle No :	SJU7357X
Date of Loss:	20/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204661/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ725K		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK075818
Reg. Date:	31/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF47KN006831
Colour:	Grey	Odometer:	41777 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,347.00	3,902.10	2,444.90	38.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,952.00	550.00	21.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,849.00	5,854.10	2,994.90	33.84
+ GST 7.00/7.00% (S\$)	619.43	409.79	209.64	33.84
Nett Amount (S\$)	9,468.43	6,263.89	3,204.54	33.84

INSPECTION

Date of Assignment:	23/08/2021		
Date Inspected:	26/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Feb 2022)

Parts: 143 AUDI A4 2.0 SEDAN TFSI S-TRONIC (NAV) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ725K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,996.00 FS	*2,996.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	459.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	223.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Scratched	249.00 FS	*248.50 FS
5	1		*REAR BUMPER TRIM	Cracked	292.00 FS	*291.50 FS
6	1		*REAR BUMPER BRACKET-RH	Not Necessary	116.00 FS	*- FS
7	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	41.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	1,063.00 FS	*- FS
9	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	46.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP	Not Necessary	166.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
13	4		*REAR PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
14	1		*EXHAUST TAIL TRIM-RH	Scratched	354.00 FS	*354.00 FS
15	1		*SUNDRIES	Necessary	300.00 FS	*12.10 FS
					Total Parts (S\$)	6,347.00 3,902.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00
3	TO RESPRAY REAR BUMPER	New	900.00	700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >