

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0682/2021/ZK
DATE : 23-Aug-21
WIP : 40656

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY26/8/2021

YOUR INSURED VEH NO : SJU 7357 X

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Hi Guo Qiang
3 days - ok - Johnny Boo
29-Sep-21

OWNER'S NAME : MR WILLIAM SOH WAI LEONG (WILLIAM SU WEILIANG)
ADDRESS : 23 ANCHORVALE CRESCENT
#14-26
SINGAPORE 544655
TELEPHONE : HP +65 9785 9505
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900012026-02
VEHICLE NO : **SMJ 725 K**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 31/1/2019
ENGINE NO : CVK 075818
CHASSIS NO : WAUZZZF47KN006831
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Aug-21
PLACE OF ACCIDENT : 23 ANCHORVALE CRESCENT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 725 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	<i>SURVEYOR'S RECOMMENDATION</i>
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 700.00
3	TO RESPRAY REAR BUMPER	\$	900.00	\$ 700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 2,502.00	\$ 1,952.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 725 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,996.00	\$ 2,996.00
2	REAR BUMPER FIXING PARTS	1	\$ 459.00	
3	REAR BUMPER SECURING STRIP	1	\$ 223.00	
4	REAR BUMPER SPOILER	1	\$ 249.00	\$ 248.50
5	REAR BUMPER TRIM	1	\$ 292.00	\$ 291.50
6	REAR BUMPER BRACKET - RH	1	\$ 116.00	
7	REAR LIGHT REFLECTOR - RH	1	\$ 41.00	
8	REAR BUMPER CARRIER	1	\$ 1,063.00	
9	REAR BUMPER CARRIER SEAL	2	\$ 28.00	
10	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 46.00	
11	REAR BUMPER HOLDING STRAP	2	\$ 166.00	
12	REAR PARKING AID SENSOR	2	TBC	
13	REAR PARKING AID SENSOR SEAL	4	\$ 14.00	
14	EXHAUST TAIL TRIM - RH	1	\$ 354.00	\$ 354.00
15	SUNDRIES		\$ 300.00	\$ 12.10
TOTAL SPARE PARTS			\$ 6,347.00	\$ 3,902.10
TOTAL LABOUR CHARGES			\$ 2,502.00	\$ 1,952.00
GRAND TOTAL			\$ 8,849.00	\$ 5,854.10

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-29/09/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT