

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 23 / 08 / 2021

ESTIMATE COSTS OF REPAIR

M/s JW Leasing Pte Ltd
C/o 160 Sin Ming Drive
#05-09 Sin Ming Auto City
Singapore 575722

*Not Authorised
L1 Sy & 5450h
Person After Pay*

Dear Sir / Madam ,

Vehicle no. : SMN 2942 R - Hyundai Avante
Accident date : 21 / 08 / 2021

Quantity	Descriptions	Amount (S\$)
1	1 pc rear bumper	\$ 459.40 ✓
2	1 pc o/s tail lamp	\$ 435.10 X
3	1 pc o/s rear bumper side retainer	\$ 31.00 ✓
4	1 pc o/s rear bumper bracket	\$ 78.60 X
5	1 pc rear bumper center garnish	\$ 353.50 X
6	1 pc o/s rear door <i>1157</i>	\$ 1,878.30 ✓
7	2 pcs o/s rear door hinge 1 @ 38.7	\$ 77.40 X
8	1 pc o/s rear door inner lock	\$ 244.50 X
9	1 pc o/s rear door checker	\$ 57.80 X
10	1 pc o/s rear door rubber(as body)	\$ 116.20 X
11	1 pc o/s rear door rubber(as door)	\$ 127.20 X
12	1 pc o/s rear door inner trimboard	\$ 497.90 X
13	1 pc o/s rear door glass outer molding	\$ 64.00 X
14	1 pc o/s rear door frame black sticker	\$ 13.10 ✓
15	1 pc o/s rear door glass regulator gear	\$ 223.40 X
16	1 pc o/s rear door glass regulator gear motor	\$ 210.20 X
17	1 pc o/s rear fender <i>1892</i>	\$ 1,892.00 ✓
18	1 pc o/s rear fender inner garnish	\$ 208.00 X
19	1 pc o/s rear shock absorber mounting	\$ 121.20 X
20	1 pc o/s rear shock absorber	\$ 239.20 X
21	1 pc o/s rear hup bearing	\$ 454.00 ✓
22	1 pc o/s rear axle beam	\$ 1,188.70 ✓
		\$ 8,970.70
	Less 20 %	\$ 1,794.14
	Balance C/FD	\$ 7,176.56

LKK AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SMN 2942 R)

\$ 7,176.56

1 pc rear windscreen glass inner seal
1 pc rear windscreen glass inner gum
1 pc n/s rear wheel tyre
1 pc n/s rear wheel rim → 20%

\$ 74.20 sn 30sn
\$ 60.00 sn 40sn
\$ 387.00 sn X
\$ 696.30 sn
\$ 8,394.06

Labour charges

\$ 1,400.00 800

To putty and spray painting

\$ 1,200.00 860

Re-seal anti rust

\$ 120.00 60

To check wiring

\$ 120.00 20

To transfer o/s rear door

\$ 120.00 60

To check wheel alignment

\$ 120.00 60

Remove and refix rear windscreen glass

\$ 180.00 120

Remove and refix cushion seat, garnish, carpet, etc

\$ 220.00 100

Remove and refix rear undercarriage

\$ 350.00 180

Add : 7% GST

\$ 12,224.06

Grand Total

\$ 855.68

\$ 13,079.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: