

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008866/R1QCN2**Date:** 05/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00005332100
Claimant Vehicle No :	SLF6456E	Insured Vehicle No :	SKT4688D
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204625/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF6456E	Engine No:	L15B4403122
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11203124
Reg. Date:	01/09/2016 (Man. Year: 2016)	Odometer:	291599 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R15	Rear Tyre Size:	215/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,630.32	6,945.00	9,685.32	58.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,120.00	2,120.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,870.32	9,065.00	11,805.32	56.57
Approved Total (Overridden) (S\$)		7,250.00		
(S\$)	20,870.32	7,250.00	13,620.32	65.26
+ GST 7.00/7.00% (S\$)	1,460.92	507.50	953.42	65.26
Nett Amount (S\$)	22,331.24	7,757.50	14,573.74	65.26

INSPECTION

Date of Assignment:	26/08/2021	
Date Inspected:	24/08/2021	Inspected At: Lion City Rental (jalan Lam Huat) (HQ) 60 Jalan Lam Huat, 04-35/36 Carros Centre Singapore 737869
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF6456E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	1,450.00 FL	*1,100.00 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*57.00 FL
3	1		*REAR TAILGATE HONDA EMBLEM	Not Necessary	81.30 FL	*- FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	86.80 FL	*- FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*165.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Necessary	155.00 FL	*155.00 FL
7	1		*REAR TAILGATE LOCK	Serviceable	550.00 FL	*- FL
8	1		*REAR RH TAILLAMP REFLECTOR	Serviceable	480.00 FL	*- FL
9	1		*REAR END PANEL	Repair	830.00 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	155.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	955.00 FL	*745.00 FL
12	1		*REAR BUMPER LH REFLECTOR	Serviceable	180.00 FL	*- FL
13	1		*REAR SPARE TYRE TOOL BOX	Serviceable	480.00 FL	*- FL
14	1		*REAR SPARE TYRE PANEL	Serviceable	2,000.00 FL	*- FL
15	1		*FRONT BONNET	Bent	1,050.00 FL	*950.00 FL
16	1		*FRONT BONNET LOCK	Serviceable	328.00 FL	*- FL
17	1		*F/L HEADLAMP	Cracked	2,100.00 FL	*1,760.00 FL
18	1		*F/L HEADLAMP TOP BRACKET	Serviceable	210.00 FL	*- FL
19	1		*F/L HEADLAMP LOWER BRACKET	Serviceable	210.00 FL	*- FL
20	1		*F/R HEADLAMP	Cracked	2,100.00 FL	*1,760.00 FL
21	1		*F/R HEADLAMP TOP BRACKET	Serviceable	210.00 FL	*- FL
22	1		*F/R HEADLAMP LOWER BRACKET	Serviceable	210.00 FL	*- FL
23	1		*FRONT BUMPER	Deformed	955.00 FL	*880.00 FL
24	1		*FRONT BUMPER REINFORCEMENT	Serviceable	680.00 FL	*- FL
25	1		*FRONT RADIATOR GRILLE BASE	Cracked	1,590.00 FL	*250.00 FL
26	1		*FRONT BUMPER LOWER LIP	Scratched	180.00 FL	*180.00 FL
27	1		*FRONT BUMPER REINFORCEMENT	Repeated	680.00 FL	*- FL
28	1		*FRONT RADIATOR CHROME MOULDING	Cracked	180.00 FL	*76.00 FL
29	1		*FRONT RADIATOR CENTER MOULDING	Cracked	780.00 FL	*197.00 FL
30	1		*FRONT RADIATOR GRILLE TOP COVER	Serviceable	80.00 FL	*- FL
31	1		*FRONT RADIATOR GRILLE HONDA EMBLEM	Not Necessary	60.00 FL	*- FL
32	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
33	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
34	1		*REVERSE SENSOR	Not Working	490.00 FS	*200.00 FS
35	1		*SET BODY SEALANT	Not Necessary	300.00 FS	*- FS
36	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*60.00 FS
37	1		*SET FRONT NUMBER PLATE	Cracked	50.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,487.90	8,600.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,857.58	1,655.00
Total Parts (\$\$)	16,630.32	6,945.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE,REAR END PANEL,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	600.00
2	TO RESPRAY REAR TAILGATE,END PANEL AND SPARE TYRE PANEL	New	800.00	400.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	40.00
5	TO CHECK WIRING SYSTEM	New	100.00	60.00
6	TO RESPRAY FRONT BUMPER,SUPPORT PANEL AND FRONT BONNET	New	900.00	400.00
7	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER AND SUPPORT PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
Gross Labour Cost (\$\$)			4,240.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >