

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

23/08/2021 11:04

JOB-NO: 50113581

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9346T

TRANS: AUTO

CHASSIS: KMHLB41UMGU092601

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU662195

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	1,400.00	0.00	1,400.00	400	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	1.00	300.00	0.00	300.00	X	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	260.00	0.00	260.00	30	Y	_____
5 TO READJUST AND REALIGN HEADLAMP AIM	1.00	140.00	0.00	140.00	X	Y	_____
6 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND INTERCOOLER TO ENABLE REPAIR	1.00	280.00	0.00	280.00	X	Y	_____
7 TO VACUUM AND TOPUP AIR COND GAS FOR A/C CONDENSER AND INTERCOOLER	1.00	250.00	0.00	250.00	X	Y	_____
8 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	160.00	0.00	160.00	X	Y	_____
9 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	200	Y	_____
10 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
11 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	200	Y	_____
12 TO RESPRAY FRONT WHEEL RIM COVER	1.00	250.00	0.00	250.00	X	Y	_____
TOTAL:		3,960.00	0.00	3,960.00			_____
MATERIALS							
1 FRONT BUMPER COVER	1.00	599.68	119.94	479.74	✓ L	Y	_____
2 FRONT BUMPER LOWER LIP	1.00	83.67	16.73	66.94	✓ L	Y	_____
3 FRONT LH BUMPER RETAINER	1.00	48.93	9.79	39.14	✓ L	Y	_____
4 FRONT LH BUMPER SIDE MOUNTING BRACKET	1.00	38.83	7.77	31.06	✓ L	Y	_____
5 FRONT BUMPER ENERGY ABSORBER	1.00	98.60	19.72	78.88	✓ L	Y	_____
6 FRONT BUMPER REINFORCEMENT	1.00	484.40	96.88	387.52	✓ L	Y	_____
7 FRONT LH BUMPER FOG LAMP GRILLE COVER	1.00	288.55	57.71	230.84	✓ L	Y	_____
8 FRONT LH BUMPER AIR DUCT	1.00	133.66	26.73	106.93	✓ L	Y	_____
9 FRONT LH HEADLAMP	1.00	1,808.60	361.72	1,446.88	✓ L	Y	_____
10 FRONT LH HEADLAMP BRACKET	1.00	52.33	10.47	41.86	✓ L	Y	_____
11 FRONT BONNET	1.00	1,812.68	362.54	1,450.14	✓ L	Y	_____
12 FRONT LH FENDER PANEL	1.00	656.70	131.34	525.36	✓ L	Y	_____
13 FRONT LH FENDER LINER	1.00	186.30	37.26	149.04	✓ L	Y	_____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
14 RADIATOR GRILLE X nn	1.00	1,110.10	222.02	888.08	L	Y	
15 RADIATOR GRILLE EMBLEM X nn	1.00	142.84	28.57	114.27	L	Y	
16 RADIATOR GRILLE CHROME MOULDING X nn	1.00	121.77	24.35	97.42	L	Y	
17 FRONT LH WHEEL RIM COVER X nn	1.00	265.20	53.04	212.16	L	Y	
18 FRONT BUMPER UPPER STRIP X nn	1.00	98.60	19.72	78.88	L	Y	
19 AIR CLEANER INTAKE RESONATOR X nn	1.00	198.67	39.73	158.94	L	Y	
20 FRONT END MODULE CARRIER ASSY X nn	1.00	986.30	197.26	789.04	L	Y	
21 FRONT BUMPER CLIP SET / nrc	1.00	80.00	0.00	80.00	S	Y	
22 FRONT BUMPER RIVET SET X - nrc	1.00	60.00	0.00	60.00	S	Y	
23 FRONT TYRE 205/60/16 X nn	1.00	350.00	0.00	350.00	S	Y	
24 FRONT FENDER LINER CLIP SET X nn	1.00	65.00	0.00	65.00	S	Y	
25 RADIATOR GRILLE CLIP SET X nn	1.00	60.00	0.00	60.00	S	Y	
26 RADIATOR COOLANT X nn	4.00	300.00	0.00	300.00	S	Y	
TOTAL:		10,131.41	843.29	8,288.12			

TOTAL PARTS & LABOUR :

14,091.41

1,843.29

12,248.12

EXCESS/LOADING:\$ 0.00

No. Of Day:

3 dy /

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

Steve (LKK) 24/8/21, 3.00pm

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2492-12
A-50
L-1060

3602-12

L/S-2881-69
2800