

KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date: 24/8/2021

Sompo Insurance Singapore Pte Ltd

50 Raffles Place, #05-01/06 Singapore Land Tower Singapore 048623

Total Pages: 1

Our Customer: Global Advance Leasing

Vehicle No: GBK4663D

Model: Toyota Hiace

Manufacture Year: 2020 Date of Accident: 23/8/2021

Total Estimate Repair Days: 3

Attn: Motor Claim Department Email: motorsurvey@sompo.com.sg

Re: Renair Estimate For Third Party Claim against: SM78564X

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	RH front fender mudflap	1	\$106.50	\$106.50	X
2	Body sticker New	1	\$180.00	\$180.00	120(SN)
	Sub Total			\$286.50	
			Less 25%	\$71.63	
	Sub Total 1			\$214.88	
B.	Special Nett				
1	Company registration sticker	1	\$30.00	\$30.00	
			Sub Total 2	\$30.00	
	Total parts			\$244.88	
C.	Labour				
1	To knock & straighten the damaged panels, remove & renew damaged parts, adjust & realign the same			\$400.00	100
2	To spray paint all affacted areas			\$600.00	400
		7	otal Labour	\$1,000.00	
		\$1,214.88			
	* The above quoted are exclusive of GST.				

Yours faithfully,

Darla

f KT Garage Pte Ltd

Surveyor's Details Name Contact Survey Date Authorize / Not Authorize Recommende Before Paint Yes / No Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Pepairer

P/P 27/08/21. 02 lap tolel: 650. (P/P)

120

300