

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

Xiao Chen.

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	21/EC/OD-348 (08)
Policy No:	MPC21P00088200	Date of Loss:	18/08/2021
Vehicle Reg. No.:	SLZ7646L	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	J MUNTRAMOORTHY	Contact No:	+6596646545
Driver:	J MUNTRAMOORTHY		
Make/Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Vehicle Reg. Date:	18/05/2018
Vehicle Colour:	Dark Blue	Chassis No:	WDC1569422J500053
Engine No:	27091031608374		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Remarks:	VEHICLE NOT IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	4,666.20
Miscellaneous Items	60.00
Labour	2,120.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,846.20
+ GST 7.00% (S\$)	479.23
Nett Amount (S\$)	7,325.43

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2021)
 Parts: 143 MERCEDES-BENZ CLA180 1.6 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SME Motor Pte Ltd/SLZ7646L/24/08/2021 12:03
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE LOGO <i>Not in</i>	0.00	0.00	*40.00 F ✓
2	1		*REAR BUMPER <i>Not in</i>	0.00	0.00	*750.00 F ✓
3	1		*REAR BUMPER RETAINER RH <i>Not in</i>	0.00	0.00	*22.00 F ✓
4	10		*REAR BUMPER CLIP <i>Not in</i>	0.00	0.00	*45.00 F ✓
5	1		*REAR BUMPER LOWER (MATT BLACK) <i>Not in</i>	0.00	0.00	*420.00 F ✓
6	1		*REAR BUMPER CORNER RH PARKING SENSOR <i>Not in</i>	0.00	0.00	*170.00 F ✓
7	1		*TAIL LAMP RH <i>Cracked</i>	0.00	0.00	*490.00 F ✓
8	1		*REAR FENDER RH <i>Distorted</i>	0.00	0.00	*1,650.00 F ✓
9	1		*REAR FENDER INNER AIR DUCT RH <i>Cracked</i>	0.00	0.00	*35.00 F ✓
10	1		*REAR FENDER PROTECTOR RH <i>Not in</i>	0.00	0.00	*175.00 F ✓
11	1		*REAR FENDER INNER COWLING RH <i>Not in</i>	0.00	0.00	*155.00 F ✓
12	10		*INNER COWLING CLIP <i>Not in</i>	0.00	0.00	*45.00 F ✓
13	1		*REAR BUMPER CENTER TOP CHROME PLATE <i>Not in</i>	0.00	0.00	*170.00 F ✓
14	1		*REAR GATE GLA 180 PLATE <i>Not in</i>	0.00	0.00	*75.00 F ✓

F=Franchise part

Sub Total (\$\$) 4,242.00
 + Margin on L,N Items 10.00% (\$\$) 424.20
 Total Parts (\$\$) 4,666.20

SME Motor Pte Ltd/SLZ7646L/24/08/2021 12:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

RH Taillamp Lower Bracket *cracked* \$65. ✓
 RH Taillamp Clips. } *x1ec* \$5. ✓
 RH Taillamp Screw } \$10. ✓

Parts: 4007

Plus 10%: 4407.70.

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR FENDER SEALANT <i>Mer</i>	60.00
Sub Total (\$\$)			60.00

60

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	40.00 <i>30</i>
2	REMOVE & REFIX CUSHION AND SEATS	New	180.00 <i>80</i>
3	LABOUR CHARGE	New	1,000.00 <i>700</i>
4	SPRAY PAINTING	New	900.00 <i>600</i>
Gross Labour Cost (\$\$)			2,120.00

1410

SME Motor Pte Ltd/SLZ7646L/24/08/2021 12:03 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian L

P/P 25/08/21

06 Days

Not Authorized

Excess: To be advised

total: 5877.70.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: