



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM21008871/Ura3q2 Date: 07/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKH 1087X	Veh. Inspected	SCJ 1828J
	Policy No.	GA071528	Coverage (\$)	0.00
	Claim No.	S1M03G8U	Excess (\$)	0.00
	Assign From		Assign Date	24/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ A180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD1760422J386990	Colour	SILVER
	Odometer	89023 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	6 mm
	L/H Front Tyre	225/45 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/08/2021	Inspection Date	24/08/2021
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	