

John Jester

not authorized
see

24/8/21

2/5 \$ 2800

3 day S.

the ph. Arthur

SCJ1828J Mercedes Benz A180

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>del/torn</i>	\$ 1,221.00
2	1	Rear bumper left bracket <i>CME</i>	\$ 73.00
3	1	Rear bumper left retainer <i>twi</i>	\$ 78.00
4	1	Rear bumper reinforcement <i>Bent</i>	\$ 387.00
5	1	Rear bumper tow cover <i>11</i>	\$ 89.00
6	1	Rear bumper lower garnish <i>del</i>	\$ 197.00
7	1	Rear left taillamp <i>CME</i>	\$ 454.00
8	1	Rear tailgate assy <i>11</i>	\$ 1,810.00
9	1	Rear tailgate inner board <i>11</i>	\$ 279.00
10	1	Rear tailgate lock mechanism <i>11</i>	\$ 251.00
11	1	Rear tailgate 'cycle and carriage' emblem <i>11</i>	\$ 68.00
12	1	Rear tailgate 'A180' emblem <i>11</i>	\$ 98.00
13	1	Rear tailgate centre logo <i>11</i>	\$ 120.00
14	1	Rear tailgate weatherstrip <i>11</i>	\$ 189.00
15	1	Rear end lower panel top garnish <i>11</i>	\$ 163.00
16	1	Rear end lower panel <i>R</i>	\$ 865.00
17	1	Rear windscreen glass moulding <i>11</i>	\$ 288.00
18	1	Rear left fender <i>11</i>	\$ 1,620.00
19	1	Rear left fender inner cowling <i>11</i>	\$ 195.00
20	1	Rear left fender inner garnish <i>11</i>	\$ 426.00
			\$ 8,871.00
less 10%			\$ 887.10
			\$ 7,983.90

Special Nett Items

1	10	Rear bumper clips <i>all</i>	\$ 60.00
2	8	Rear tailgate inner board clips <i>11</i>	\$ 40.00
3	4	Rear end lower panel top garnish clips <i>11</i>	\$ 30.00
4	1	Rear end lower panel sealant <i>11</i>	\$ 120.00
5	1	Rear windscreen glass sealant <i>11</i>	\$ 100.00
6	4	Rear bumper reverse sensor <i>should 11</i>	\$ 1,200.00
7	1	Rear no plate with garnish <i>11</i>	\$ 100.00
8	4	Rear left fender inner cowling clips <i>11</i>	\$ 30.00
9	6	Rear left fender inner garnish clips <i>11</i>	\$ 40.00
10	1	Rear left fender sealant <i>11</i>	\$ 100.00
			\$ 1,820.00

Total parts

\$ 9,803.90

P-2410

10%

P-2169

S.N-240

SCJ1828J Mercedes Benz A180

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear left affected area and replace rear left damaged parts.	\$ 1,000.00	400
2	To putty and spray painting rear left portion.	\$ 1,000.00	600
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 1180.00	X
5	To remove and install rear fuel tank to facilitate the repair.	\$ 1180.00	X
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	80
7	To apply anti rust proofing to rear left affected area.	\$ 1140.00	X
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 1140.00	X
10	Towing service.	\$ 1100.00	X
Total labour :		\$ 2,910.00	

Total parts : \$ 9,803.90

Total labour : \$ 2,910.00

Total repair cost : \$ 12,713.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: