

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: LIM.513171.Q Date: 09th Sep 2021

Our Ref: CS1/LAW21008876/T1tce2

## M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJL 7274Z INSURED VEHICLE: FBJ 5105Y ACCIDENT DATE: 08/12/2018

We thank you for your instruction on 04/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJL 7274Z from M/s Sincere Appraisal Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SJL 7274Z and FBJ 5105Y.
- c) Final Repair Bill of SJL 7274Z from M/s 28 Auto Werkz Pte Ltd.
- d) Colour damaged vehicle photographs of SJL 7274Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJL 7274Z

Make & Model : Mitsubishi Lancer 1.5 Mivec GLS 4A/T

Chassis Number : JMYSRCY2A9U002023

Year of Registration : 2008 Engine Capacity : 1499 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.