

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TOH BOON TAK  
 BLK 335 JURONG EAST AVE 1 #01-1580  
 SINGAPORE 600335

Contact : 97451479

TP China  
 Denise

## ESTIMATE

Repair Code : CLM16910  
 Date in : 23/08/2021  
 Vehicle Num. : SLK2582Z  
 Model : HONDA SHUTTLE 1.5G CVT  
 Chassis/Eng# : GK81100945/L15B5001131

### Parts and Labour Assesment

| Description of part                               | Qty | Unit Price | Amount     |
|---------------------------------------------------|-----|------------|------------|
| AIRCON CONDENSER <i>Dented</i>                    | 1   | 1050.00    | ✓ 1,050.00 |
| AIRCON CONDENSER ALUMINIUM PIPE <i>Bent</i>       | 1   | 180.00     | ✓ 180.00   |
| AIRCON CONDENSER DISCHARGE PIPE                   | 1   | 210.00     | ✓ 210.00   |
| AIRCON CONDENSER FAN BLADE <i>cut</i>             | 1   | 78.00      | ✓ 78.00    |
| AIRCON CONDENSER FAN COWLING <i>del</i>           | 1   | 93.90      | ✓ 93.90    |
| AIRCON CONDENSER FAN MOTOR <i>new</i>             | 1   | 310.00     | + 310.00   |
| AIRCON CONDENSER SUCTION PIPE <i>new</i>          | 1   | 178.00     | + 178.00   |
| FRONT BONNET <i>Dented</i>                        | 1   | 920.80     | ✓ 920.80   |
| FRONT BONNET HINGES L/R <i>Bent</i>               | 2   | 40.00      | ✓ 80.00    |
| FRONT BONNET INNER TOP RUBBER MOULDING <i>new</i> | 1   | 98.50      | + 98.50    |
| FRONT BONNET INSULATOR <i>new</i>                 | 1   | 140.00     | + 140.00   |
| FRONT BONNET MECHANISM LOCK <i>Dented</i>         | 1   | 135.00     | ✓ 135.00   |
| FRONT BUMPER <i>Distorted</i>                     | 1   | 1050.00    | ✓ 1,050.00 |
| FRONT BUMPER FOGLAMP GARNISH L/R <i>del</i>       | 2   | 25.00      | ✓ 50.00    |
| FRONT BUMPER LOWER GRILLE <i>del</i>              | 1   | 140.00     | ✓ 140.00   |
| FRONT BUMPER REINFORCEMENT <i>Dented</i>          | 1   | 420.90     | ✓ 420.90   |
| FRONT BUMPER SIDE GARNISH L/R <i>del</i>          | 2   | 33.20      | ✓ 66.40    |
| FRONT BUMPER SIDE RETAINER L/R <i>new</i>         | 2   | 15.70      | ✓ 31.40    |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

**TOH BOON TAK**  
 BLK 335 JURONG EAST AVE 1 #01-1580  
 SINGAPORE 600335

Contact : 97451479

## ESTIMATE

Repair Code : CLM16910

Date in : 23/08/2021

Vehicle Num. : SLK2582Z

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng# : GK81100945/L15B5001131

|                                          |                           |   |         |                |                   |
|------------------------------------------|---------------------------|---|---------|----------------|-------------------|
| FRONT BUMPER TOW HOOK COVER              | <i>Deled</i>              | 1 | 58.20   | ✓              | 58.20             |
| FRONT BUMPER UNDER COVER                 | <i>Deled</i>              | 1 | 210.40  | ✓              | 210.40            |
| FRONT FENDER INNER BRACKET L/R           | <i>LH Bert</i>            | 2 | 98.00   | ✓              | 196.00            |
| FRONT FENDER INNER SHIELD L/R            | <i>new</i>                | 2 | 110.50  | +              | 221.00            |
| FRONT FENDER L/R                         | <i>LH Bucked</i>          | 2 | 435.00  | <del>435</del> | <del>870.00</del> |
| FRONT GRILLE                             | <i>could</i>              | 1 | 395.00  | ✓              | 395.00            |
| FRONT GRILLE 'H' EMBLEM                  | <i>new</i>                | 1 | 23.40   | ✓              | 23.40             |
| FRONT GRILLE CENTER BRACKET              | <i>could</i>              | 1 | 65.00   | ✓              | 65.00             |
| FRONT GRILLE CHROME MOULDING             | <i>could new</i>          | 1 | 98.70   | +              | 98.70             |
| FRONT GRILLE OUTER CHROME COVER          | <i>could</i>              | 1 | 302.50  | ✓              | 302.50            |
| FRONT GRILLE TOP GARNISH                 | <i>Deled</i>              | 1 | 58.20   | ✓              | 58.20             |
| FRONT HEADLAMP 'L.E.D' L/R               | <i>could</i>              | 2 | 2250.00 | ✓              | 4,500.00          |
| FRONT HEADLAMP LOWER BRACKET L/R         | <i>could</i>              | 2 | 38.00   | ✓              | 76.00             |
| FRONT HEADLAMP OUTER CHROME MOULDING L/R | <i>LH Missing, RH not</i> | 2 | 86.00   | —              | 172.00            |
| FRONT HORN                               | <i>Bert</i>               | 1 | 48.60   | ✓              | 48.60             |
| FRONT INTAKE AIR DUCT                    | <i>new</i>                | 1 | 80.60   | +              | 80.60             |
| FRONT RESONATOR                          | <i>new could</i>          | 1 | 188.00  | +              | 188.00            |
| FRONT RESONATOR TUBE                     | <i>new</i>                | 1 | 56.00   | +              | 56.00             |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*



Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TOH BOON TAK  
 BLK 335 JURONG EAST AVE 1 #01-1580  
 SINGAPORE 600335

Contact : 97451479

## ESTIMATE

Repair Code : CLM16910  
 Date in : 23/08/2021  
 Vehicle Num. : SLK2582Z  
 Model : HONDA SHUTTLE 1.5G CVT  
 Chassis/Eng# : GK81100945/L15B5001131

|                                                   |          |   |         |   |           |
|---------------------------------------------------|----------|---|---------|---|-----------|
| FRONT SUPPORT PANEL                               | Builed.  | 1 | 760.40  | ✓ | 760.40    |
| FRONT SUPPORT PANEL INNER RUBBER SIDE STOPPER L/R | not in   | 2 | 15.00   | + | 30.00     |
| RADIATOR (AUTO)                                   | Perished | 1 | 1350.00 | ✓ | 1,350.00  |
| RADIATOR FAN BLADE                                | } new    | 1 | 78.00   | + | 78.00     |
| RADIATOR FAN COWLING                              |          | 1 | 89.30   | + | 89.30     |
| RADIATOR FAN MOTOR                                |          | 1 | 219.00  | + | 219.00    |
| RADIATOR LOWER HOSE                               |          | 1 | 76.80   | + | 76.80     |
| RADIATOR SIDE GUIDE L/R                           | Del d    | 2 | 50.10   | ✓ | 100.20    |
| RADIATOR SPARE TANK                               | Del d    | 1 | 40.10   | ✓ | 40.10     |
| RADIATOR TOP BRACKET L/R                          | new      | 2 | 16.50   | + | 33.00     |
| RADIATOR TOP HOSE                                 | new      | 1 | 45.00   | + | 45.00     |
| WASHER TANK                                       | } new    | 1 | 75.00   | + | 75.00     |
| WASHER TANK MOTOR                                 |          | 1 | 48.60   | + | 48.60     |
| WASHER TANK NECK                                  |          | 1 | 27.50   | + | 27.50     |
| Subtotal before discount                          |          |   |         |   | 15,825.40 |
| Percentage discount 20%                           |          |   |         |   | 3,165.08  |
| Sub-total 1                                       |          |   |         |   | 12,660.32 |
| FRONT BONNET INSULATOR CLIPS - SET                | Not in   | 1 | 50.00   | + | 50.00     |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

TOH BOON TAK  
BLK 335 JURONG EAST AVE 1 #01-1580  
SINGAPORE 600335

Contact : 97451479

## ESTIMATE

Repair Code : CLM16910

Date in : 23/08/2021

Vehicle Num. : SLK2582Z

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng# : GK81100945/L15B5001131

|                                                      |   |       |    |                  |
|------------------------------------------------------|---|-------|----|------------------|
| FRONT BUMPER CLIPS - SET <i>new</i>                  | 1 | 50.00 | ✓  | 50.00            |
| FRONT BUMPER NUMBER PLATE <i>lit</i>                 | 1 | 25.00 | ✓  | 25.00            |
| FRONT BUMPER NUMBER PLATE HOLDER <i>lit</i>          | 1 | 50.00 | 30 | <del>50.00</del> |
| FRONT FENDER INNER SHIELD CLIPS L/R - SET <i>new</i> | 2 | 40.00 | ←  | 80.00            |
| FRONT GRILLE CLIPS - SET <i>new</i>                  | 1 | 50.00 | 20 | <del>50.00</del> |
| RADIATOR COOLANT <i>new</i>                          | 1 | 80.00 | 40 | <del>80.00</del> |
| Subtotal before discount                             |   |       |    | 385.00           |
| Percentage discount 0%                               |   |       |    | 0.00             |
| Sub-total 2                                          |   |       |    | 385.00           |
| Parts-total                                          |   |       |    | 13,045.32        |

## LABOUR

To remove, change air con parts, vacuums, refill air con gas. ✓ 120.00

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR) 30 80.00

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper. 900 1,100.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. 800 1,000.00

To apply anti-rust chemical on repaired and replaced panel. 60 120.00

Labour Total

2,420.00

Parts & Labour Total

15,465.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 4

Adam L  
h/s 24/08/21

06 Days

total: 13163.32

h/s: 10.5K ✓