



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2107959

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 18/11/2021
Reference CC4/LPC21008883/Ues3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 7674K
Insured Veh. GBD 2902P
Claim No. 21/21/21/VC00/024877
Policy No. Z/21/VC00/111741
Accident Date 23/08/2021
Inspection Date 30/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21008883/Ues3q2	
			Date: 18/11/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2902P	Veh. Inspected	SLF 7674K	
Policy No.	Z/21/VC00/111741	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024877	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	24/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850HX200539	Colour	BLACK	
Odometer	110041 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	MICHELIN	7 mm	
L/H Front Tyre	185/55 R16	MICHELIN	7 mm	
R/H Rear Tyre	185/55 R16	MICHELIN	7 mm	
L/H Rear Tyre	185/55 R16	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/08/2021	Inspection Date	30/08/2021	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7674K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
2	RUBBERWINDSHIELD DAMPER (SN)	NECESSARY	11.10	11.10
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	9.15	9.15
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.82	6.82
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE COMP (SN)	BADLY DENTED	584.40	584.40
1	WEATHERSTRIPTAILGATE (SN)	NOT NECESSARY	69.22	-
1	LOCK ASSY, TAILGATE (SN)	NOT NECESSARY	67.57	-
1	EMBLEMRR (SN)	NECESSARY	9.30	9.30
1	FACERR.BUMPER (SN)	DENTED / DEFORMED	401.92	401.92
5	CLIP,BUMPER (SN)	NECESSARY	8.62	8.62
1	SPACERL.RR.BUMPER (SN)	BENT	8.62	8.62
1	SPACERR.RR.BUMPER (SN)	BENT	8.62	8.62
1	GARNISHL.RR.BUMPER (SN)	NOT NECESSARY	11.40	-
1	GARNISHR.RR.BUMPER (SN)	NOT NECESSARY	11.40	-
4	ACT RR.SENSOR (SN)	SERVICEABLE	320.00	-
1	PANEL COMPRR (SN)	DENTED	256.20	256.20
1	LINING ASSY ,RR PANEL (SN)	NOT NECESSARY	45.60	-
1	BODY JOINT SEALANT (SN)	NECESSARY	100.00	100.00
			2,039.94	1,484.75
	<u>LABOUR</u>			
	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER		180.00	130.00
	REMOVE & REFIX REVERSE SENSORS .		200.00	150.00
	BODY UNDERSIDE COATING.		100.00	100.00
	APPLY BODY UNDERSIDE COATING.		250.00	180.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		450.00	320.00
	RESET VEHICLE SMART ENTRY SYSTEM.		450.00	350.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		450.00	350.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &.		650.00	450.00
	REMOVE & INSTALL RR WINDSCREEN .		650.00	650.00
	CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN.		2,800.00	2,300.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS .		2,800.00	2,600.00
			8,980.00	7,580.00
GRAND TOTAL			11,019.94	9,064.75
RECOMMENDED COST OF REPAIRS				9,064.75

Report Ref No. CC4/LPC21008883/Ues3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 7674K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 7674K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

