

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21002624	Page	1
Registration No	: SLF7674K	Date	: 23. Aug 2021	Customer No.	: WZL009
Chassis No	: JHMGK5850HX200539	Svc Advisor	: RUEBEN THOMAS	Engine No	: L15B31190293
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 23. Aug 2021 5:02:50 PM	Surveyor Name	:
Owner's Name	: ONG WAH LIAT	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 23/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG WAH LIAT OWNER INSURER: LIBERTY INSURANCE ACC DATE: 23/08/2021 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE TP VEH: GBD2902P						
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	12.20	25	9.15	0.64	9.79
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	7.40	25	11.10	0.78	11.88
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP	1	779.20	25	584.40	40.91	625.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE	1	90.10	25	67.57	4.73	72.30
75722-T5L-T01	EMBLEMRR.	1	12.40	25	9.30	0.65	9.95
04715-T5B-000ZZ	FACERR.BUMPER	1	535.90	25	401.92	28.13	430.05
91505-TM8-003	CLIP,BUMPER	5	2.30	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71507-T5A-000	GARNISHL.RR.BUMPER	1	15.20	25	11.40	0.80	12.20
71502-T5A-000	GARNISHR.RR.BUMPER	1	15.20	25	11.40	0.80	12.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
66100-TAR-T10ZZ	PANEL COMPRR.	1	341.60	25	256.20	17.93	274.13
84640-T5A-003ZA	LINING ASSY,RR.PANEL	1	60.80	25	45.60	3.19	48.79
Sum Item					1889.94	132.29	2,022.23

Printed on 23/8/2021 5:50:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21002624	Page	2
Registration No	: SLF7674K	Date	: 23. Aug 2021		
Chassis No	: JHMGK5850HX200539	Customer No.	: WZL009		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: ONG WAH LIAT	Engine No	: L15B31190293		
Ins Policy No.	:	Date Time	: 23. Aug 2021 5:02:50 PM		
Date of Accident	: 23/8/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2800.00		2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00		2800.00	196.00	2996.00
Sum Labor					9130.00	639.10	9,769.10

Survey By							
Date & Time					Total Amount	11,019.94	771.39
Excess					Total (Inclusive of GST)		11,791.33
Status							
Signature							

Printed on 23/8/2021 5:50:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.