

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT21002624	Page	1
	300 BEACH ROAD #17-04/07	Date	: 23. Aug 2021		
	THE CONCOURSE	Customer No.	: WZL009		
	SINGAPORE 199555	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLF7674K	Engine No	: L15B31190293		
Chassis No	: JHMGK5850HX200539	Date Time	: 23. Aug 2021 5:02:50 PM		
Model	: JAZZ 1.5VTIR CVT 17YM	Surveyor Name	:		
Owner's Name	: ONG WAH LIAT	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 23/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: ONG WAH LIAT						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 23/08/2021						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC INSURANCE						
	TP VEH: GBD2902P						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>all</i>	1	12.20	25	9.15	0.64	9.79
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>all</i>	2	7.40	25	11.10	0.78	11.88
73226-SZW-000	DAMPERSTD 5X5 <i>all</i>	1	9.10	25	6.82	0.48	7.30
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>all</i>	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP <i>Body DO</i>	1	779.20	25	584.40	40.91	625.31
74440-T5A-003	WEATHERSTRIPTAILGATE <i>11</i>	1	92.30	X 25	69.22	X 4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE <i>11</i>	1	90.10	X 25	67.57	X 4.73	72.30
75722-T5L-T01	EMBLEMRR. <i>all</i>	1	12.40	25	9.30	0.65	9.95
04715-T5B-000ZZ	FACERR.BUMPER <i>DO/DR</i>	1	535.90	25	401.92	28.13	430.05
91505-TM8-003	CLIP,BUMPER <i>all</i>	5	2.30	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>all</i>	1	11.50	25	8.62	0.60	9.22
71593-T5A-000	SPACERR.RR.BUMPER <i>all</i>	1	11.50	25	8.62	0.60	9.22
71507-T5A-000	GARNISHL.RR.BUMPER <i>11</i>	1	15.20	X 25	11.40	X 0.80	12.20
71502-T5A-000	GARNISHR.RR.BUMPER <i>11</i>	1	15.20	X 25	11.40	X 0.80	12.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>DO</i>	1	320.00	?	320.00	?	342.40
66100-TAR-T10ZZ	PANEL COMPRR. <i>DO</i>	1	341.60	25	256.20	17.93	274.13
84640-T5A-003ZA	LINING ASSY,RR.PANEL <i>11</i>	1	60.80	X 25	45.60	X 3.19	48.79
Sum Item					1889.94	132.29	2,022.23

Printed on 23/8/2021 5:50:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21002624	Page	2
Registration No	: SLF7674K	Date	: 23. Aug 2021		
Chassis No	: JHMGK5850HX200539	Customer No.	: WZL009		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: ONG WAH LIAT	Engine No	: L15B31190293		
Ins Policy No.	:	Date Time	: 23. Aug 2021 5:02:50 PM		
Date of Accident	: 23/8/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	130	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00	150	200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	320	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350	450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	450	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2800.00	2300	2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00	1600	2800.00	196.00	2996.00
Sum Labor					9130.00	639.10	9,769.10

Survey By Marcus Hui
Date & Time 30/8/21 @ 3pm.
Excess —
Status N.A. Adherent
Signature Take place subsequently.
7 days

Total Amount 11,019.94 771.39 11,791.33
Total (Inclusive of GST) 11,791.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 23/8/2021 5:50:27 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.