

08/11/13 wef

ASS. REC. BY: *MACILS*

REF: *CC4/LAC21028883/4253*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLF7674K*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *\$52K.*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *6* days Res.: Yes or No

Lum Sum: *131* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

013E

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/9/13 17:45 35457

Veh No: *SLF7674K*

Yr Regn: *08/09/16*

Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *41*

Make: *Honda Jazz*

c.c *1498*

Colour *Black*

A/C: Insured / Std / NI / NA

Sp. Reading *110041*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *JHM6K5850HX200539*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Normal* / Jammed / Leaked / Burnt or

Brake: *Normal* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: *185/55R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / *MIT* / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A. *23/8/11*

D.O.I. *30/8/11*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

27/9/13 P/P \$9064.75 confirmed with Ruben



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21002624	Page	1
Registration No	: SLF7674K	Date	: 23. Aug 2021		
Chassis No	: JHMGK5850HX200539	Customer No.	: WZL009		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: ONG WAH LIAT	Engine No	: L15B31190293		
Ins Policy No.	:	Date Time	: 23. Aug 2021 5:02:50 PM		
Date of Accident	: 23/8/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG WAH LIAT OWNER INSURER: LIBERTY INSURANCE ACC DATE: 23/08/2021 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE TP VEH: GBD2902P						
73127-TY0-000	RUBBER C WINDSHIELD DAMPER <i>neu</i>	1	12.20	25	9.15	0.64	9.79
73214-T5A-013	RUBBER WINDSHIELD DAMPER <i>neu</i>	2	7.40	25	11.10	0.78	11.88
73226-SZW-000	DAMPER STD 5XS <i>neu</i>	1	9.10	25	6.82	0.48	7.30
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP <i>Body DO</i>	1	779.20	25	584.40	40.91	625.31
74440-T5A-003	WEATHER STRIP TAILGATE <i>11</i>	1	92.30	X 25	69.22	X 4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE <i>11</i>	1	90.10	X 25	67.57	X 4.73	72.30
75722-T5L-T01	EMBLEM RR. <i>neu</i>	1	12.40	25	9.30	0.65	9.95
04715-T5B-000ZZ	FACERR. BUMPER <i>DO/RR neu</i>	1	535.90	25	401.92	28.13	430.05
91505-TM8-003	CLIP, BUMPER <i>neu</i>	5	2.30	25	8.62	0.60	9.22
71598-T5A-000	SPACER L. RR. BUMPER <i>sent</i>	1	11.50	25	8.62	0.60	9.22
71593-T5A-000	SPACER R. RR. BUMPER <i>sent</i>	1	11.50	25	8.62	0.60	9.22
71507-T5A-000	GARNISH L. RR. BUMPER <i>11</i>	1	15.20	X 25	11.40	X 0.80	12.20
71502-T5A-000	GARNISH R. RR. BUMPER <i>11</i>	1	15.20	X 25	11.40	X 0.80	12.20
NMRS-4P-TM3040L	4PCS ACT RR. SENSOR <i>SVC</i>	1	320.00	X	320.00	X 22.40	342.40
66100-TAR-T10ZZ	PANEL COMPRR. <i>DO</i>	1	341.60	25	256.20	17.93	274.13
84640-T5A-003ZA	LINING ASSY, RR. PANEL <i>11</i>	1	60.80	X 25	45.60	X 3.19	48.79
Sum Item					1889.94	132.29	2,022.23

Printed on 23/8/2021 5:50:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21002624	Page	2
Registration No	: SLF7674K	Date	: 23. Aug 2021		
Chassis No	: JHMGK5850HX200539	Customer No.	: WZL009		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: ONG WAH LIAT	Engine No	: L15B31190293		
Ins Policy No.	:	Date Time	: 23. Aug 2021 5:02:50 PM		
Date of Accident	: 23/8/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	130	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00	150	200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT.	1	100.00	✓	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	320	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350	450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	450	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	✓	650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2800.00	2300	2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00	1600	2800.00	196.00	2996.00
Sum Labor					9130.00	639.10	9,769.10

Survey By: morans HHH
Date & Time: 30/8/21 @ 3pm.
Excess: —
Status: N.F. Adherent
Signature: Take John Sekhargany.
G. J. J.

Total Amount 11,019.94 771.39 11,791.33
Total (Inclusive of GST) 11,791.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 23/8/2021 5:50:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

16/1/2021

Page 1/2

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

ATTN: MARCUS

WD: 6 DAYS

Customer: CU0116614 / LONPAC
 Chassis No: JHMGK5850HX200539
 License No: SLF7674K
 Mileage: 110041
 Engine No: L15B31190293

Document No: SVO21044758
 Printed By: JESHURUEBEN
 Order Date: 30. August 2021
 Order Time: 3:33:37 PM
 Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO: 76447)						
	OWNER: ONG WAH LIAT						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 23/08/2021						
	SURVEYED BY: MARCUS (LKK)						
	DATE: 30/08/2021						
	REF NO:						
	TP INSURER: LONPAC INSURANCE						
	TP VEH: GBD2902P						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	12.20	25	9.15	0.64	9.79
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.40	25	11.10	0.78	11.88
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP	1	779.20	25	584.40	40.91	625.31
75722-T5L-T01	EMBLEMRR.	1	12.40	25	9.30	0.65	9.95
04715-T5B-000ZZ	FACERR BUMPER	1	535.90	25	401.92	28.13	430.05
91505-TM8-003	CLIP,BUMPER	5	2.30	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
66100-TAR-T10ZZ	PANEL COMPRR.	1	341.60	25	256.20	17.93	274.13
	SUM PARTS:				1,364.75	95.52	1,460.27
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	130.00		130.00	9.10	139.10
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BA02R	EXT-YJ	1	150.00		150.00	10.50	160.50
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BOJSE	0760	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						
BOBC	0959	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BMI03D	EXT-YJ	1	320.00		320.00	22.40	342.40
	REMOVE & INSTALL REAR						
	COMPARTMENT LININGS						
	GARNISHES.(N)						
BC012R	0760	1	350.00		350.00	24.50	374.50
	RESET VEHICLE SMART ENTRY						
	SYSTEM						
BC011R	0760	1	350.00		350.00	24.50	374.50
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BKTG02R	EXT-YJ	1	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW						
	TAILGATE. ADJUST &						
	ALIGN TAILGATE.(N)						

**HONDA****SERVICE PRE-INVOICE**

PAGE 2/2

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0116614 / LONPAC
Chassis No: JHMGK5850HX200539
License No: SLF7674K
Mileage: 110041
Engine No: L15B31190293

Document No: SVO21044758
Printed By: JESHURUEBEN
Order Date: 30. August 2021
Order Time: 3:33:37 PM
Service Advisor: RUEBEN THOMAS

BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	650.00	650.00	45.50	695.50
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	2,300.00	2,300.00	161.00	2,461.00
BP05R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,600.00	2,600.00	182.00	2,782.00
			SUM LABOUR:	7,700.00	539.00	8,239.00
			TOTAL SGD	9,084.75	634.52	9,699.27
			Total Payable (SGD)			9,699.27

GST Amount is calculated from individual line(s)