



Borneo Motors

Inchcape


Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TP/DS Repair

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tau Wen Jun Andrew (Tu WenJun) 35B Nim Road Singapore 805071 Mobile: 97606567		
			Document No. 0				
			Document Date 01/09/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800067075		2NRX522799	60	Raymond Seah L M	26/08/2021	12.56	27/08/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:GBK7023G ACC DATE:22/08/2021 TP INS:CHINA TAIPING NO OF REPAIR DAYS:07 DATE-IN:26/08/2021 DATE SURVEY:26/08/2021 BY:LKK-GUO QIANG AUTHORISED ON: -TP/DS CLAIM				30.00	
2	S	BP-SUBLET SUPPLY SEALANT (NETT) FOR REAR TAILGATE	0742			60.00	
3	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
4	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.	0741			400.00	
5	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	0742			122.40	
6	S	BP-SUBLET R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.	0742			180.00	
7	S	BP-SUBLET R/I REAR WINDSCREEN TO FACILITATE REPAIRS AND WATER TEST.	0742			396.00	
8	S	BP-SUBLET TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILITATE REPAIRS.	0742			360.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tau Wen Jun Andrew (Tu WenJun) 35B Nim Road Singapore 805071 Mobile: 97606567		
			Document No.				
			0				
			Document Date				
			01/09/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800067075		2NRX522799	60	Raymond Seah L M	26/08/2021	12.56	27/08/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	S	BP-SUBLET R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			360.00	
10	S	BP-SUBLET TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	0742			2160.00	
11	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	0742			1770.00	
12	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				183.18	
13	1	T81561-52C90 LENS & BODY, RR	1.00	369.40		369.40	
14	2	S52159-0U919 COVER, RR BUMPER, L	1.00	319.20		319.20	
15	3	S52151-0D010 EXTENSION, RR BUMPER	1.00	191.80		191.80	
16	4	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00	
17	5	S68105-0D261 GLASS SUB-ASSY, BACK2	1.00	1041.50		1041.50	
18	6	T21000-20 SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00		216.00	
19	7	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIMER	1.00	200.00		200.00	
20	8	S64813-0D330 DAM, BACK WINDOW GLA	2.00	12.50		25.00	
21	9	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1142.50		1142.50	
22	0	T90975-02086 EMBLEM,SYMBOL	1.00	72.20		72.20	
23	1	S75442-0D290 PLATE, BACK DOOR NAM	1.00	35.80		35.80	
24	2	S75441-0D070 PLATE, BACK DOOR NAM	1.00	53.70		53.70	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA


ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tau Wen Jun Andrew (Tu WenJun) 35B Nim Road Singapore 805071 Mobile: 97606567		
			Document No.				
			0				
			Document Date				
			01/09/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3800067075	2NRX522799	60	Raymond Seah L M	26/08/2021 12.56	27/08/2021 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	3	S76801-0D600 GARNISH SUB-ASSY, BA	1.00	231.80		231.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary		Total	10,141.48
		Please acknowledge receipt of vehicle	Parts	3,939.90	GST 7.00%	709.90
			Labour	30.00		
			Sublet	6,171.58	Less	0.00
			Lubrication/Fluid	0.00		
			Others	0.00		
				Amount Due	10,851.38	

Company Copy

Vehicle Diagnostic Report

2NRFE
035245 km

MHFZ28H3800067075

Borneo Motors

Printed By: Default User(1)

01/09/2021 3:07:52 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT	Yes	P0113	X	X	X		-	30U12100 A0202000	No
ABS/VSC/TRC	Yes	C1201	X		X		-	F1526526 21	No
EMPS							-	8965B0D 110	No
Air Conditioner							-	886500D5 8001	No
Combination Meter							-	838000U A2002	No
							-	838005C P6003	
Entry&Start							-	-	No
Rear Left Door							-	859180D0 7001	No
Rear Right Door							-	859180D0 8001	No
SRS Airbag							-	8917F0D3 31	No
Starting Control							-	-	No
Power Source Control							-	-	No
HL AutoLeveling							-	-	No

Vehicle Diagnostic Report

2NRFE
035245 km

MHFZ28H3800067075

Borneo Motors

Printed By: Default User(1)

01/09/2021 3:08:58 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT							-	30U12100 A0202000	No
ABS/VSC/TRC							-	F1526526 21	No
EMPS							-	8965B0D 110	No
Air Conditioner							-	886500D5 8001	No
Combination Meter							-	838000U A2002	No
								838005C P6003	
Entry&Start							-	-	No
Rear Left Door							-	859180D0 7001	No
Rear Right Door							-	859180D0 8001	No
SRS Airbag							-	8917F0D3 31	No
Starting Control							-	-	No
Power Source Control							-	-	No
HL AutoLeveling							-	-	No