

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

24/08/2021 14:37

JOB-NO: 50113563

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9113Z

TRANS: AUTO

CHASSIS: KMHLB41UMGU085506

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDEU440392

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	1,400.00	0.00	1,400.00	400	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	1.00	280.00	0.00	280.00	X	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	220.00	0.00	220.00	30	Y	_____
5 TO REFIT REAR REVERSE SENSOR	1.00	150.00	0.00	150.00	30	Y	_____
6 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	160.00	0.00	160.00	60	Y	_____
7 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200	Y	_____
8 TO RESPRAY REAR BUMPER LOWER	1.00	250.00	0.00	250.00	X	Y	_____
9 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	X	Y	_____
10 TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
11 TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	X	Y	_____
12 TO RESPRAY SIDE SKIRT RH	1.00	250.00	0.00	250.00	X	Y	_____
TOTAL:		3,880.00	0.00	3,880.00			_____
<u>MATERIALS</u>							
1 REAR BUMPER COVER X R (Disrupt (hick))	1.00	599.68	119.94	479.74	L	Y	_____
2 REAR RH BUMPER RETAINER X nn	1.00	58.60	11.72	46.88	L	Y	_____
3 REAR BUMPER ENERGY ABSORBER X nn	1.00	99.62	19.92	79.70	L	Y	_____
4 REAR BUMPER LOWER X nn	1.00	228.40	45.68	182.72	L	Y	_____
5 REAR WHEEL RIM COVER / CUT	1.00	265.50	53.10	212.40	L	Y	_____
6 REAR RH FENDER LINER X nn	1.00	178.88	35.78	143.10	L	Y	_____
7 REAR RH QUARTER PANEL AIR VENT X nn	1.00	89.88	17.98	71.90	L	Y	_____
8 REAR BUMPER CLIP SET X nn	1.00	80.00	0.00	80.00	S 20	Y	_____
9 REAR BUMPER LOWER CLIP X nn	1.00	70.00	0.00	70.00	S	Y	_____
10 REAR FENDER LINER CLIP SET X nn	1.00	65.00	0.00	65.00	S	Y	_____
11 ROCKER PANEL MOULDING CLIP X nn	1.00	60.00	0.00	60.00	S	Y	_____
12 REAR DOOR "COMFORT DELGRO" STICKER X nn	1.00	140.00	0.00	140.00	S	Y	_____
13 REAR DOOR "GOOGLE PLAY STORE" "APP STORE" STICKER X nn	1.00	140.00	0.00	140.00	S	Y	_____
14 TAILLAMP GUIDE CLIP SET X nn	1.00	50.00	0.00	50.00	S	Y	_____
TOTAL:		2,125.56	304.12	1,821.44			_____
TOTAL PARTS & LABOUR :		6,005.56	304.12	5,701.44			_____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:\$ 0.00

No. Of Day:

3 days

L/S, My AL by

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

25/8/21, 19.37

SURVEYED BY:

Steve (LKK)

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: