



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Business Reg. No.: 53387981K

Tel: 9101 7844

Fax: 6996 6442

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/2008/FBJ2330H/PR

ASSESSMENT FOR REPAIR : FBJ2330H

Qty	Description	Condition	Repairer's Estimate	Our Assessment
2 pcs	Handle bar @309.00	Usable	618.00	~
1 set	Handle bar end	Cut	80.00	80.00 60
2 pcs	Throttle cable complete @76.00	Cut	152.00	152.00 ✓
2 pcs	Mirror assy @338.00 298	Cut	676.00	676.00 596
2 pcs	Front winker lens complete @99.00	Usable	198.00	~
1 pc	Windscreen	Usable	442.00	~
1 pc	Upper cowling set	Cracked	1,705.00	1,705.00 980
1 pc	Headlight unit	Broken	2,013.00	2,013.00 1445
1 pc	Front stay xsvc	Bent	393.00	393.00 x
1 pc	Front fender set repair	Cut	504.00	504.00 x
2 pcs	Air duct top side cover assy @108.00	LH Broken	216.00	108.00 ✓
2 pcs	Mid cowling set @1687.00 1105	Broken / Cut	3,374.00	3,374.00 2210
2 pcs	Mid cowling layer @125.00	Grazed / Cut	250.00	250.00 ✓
2 pcs	Under cowling set @912.00 520	Grazed / Cut	1,824.00	1,824.00 1040
1 pc	Brake pedal	Cut & Bent	228.00	228.00 130
1 pc	Front step assy RH	Cut	173.00	173.00 120
1 pc	Rear step assy RH	Cut	157.00	157.00 110
1 pc	Muffler cover	Cut	169.00	169.00 ✓
1 pc	Muffler guard complete xnn	Cut & Dented	601.00	601.00 x
1 pc	Muffler assy	Dented	3,192.00	3,192.00 2200
			9570	
			10%	
			8613	
		Less 10%	16,965.00	15,599.00
			1,696.50	1,559.90
			<u>15,268.50</u>	<u>14,039.10</u>
<u>Special Nett Items</u>				
1 set	Steering cone & bearing	Necessary / 50%	212.00	106.00 ✓
1 pc	Handle guard	Cracked	312.00	312.00 120
1 pc	Engine cover set, GB Racing	Cut	486.00	486.00 320
			1,010.00	904.00
Total Parts			<u>16,278.50</u>	<u>14,943.10</u>
<u>Labour Charges</u>				
1	Towing fee		80.00	60.00 40
2	Repair forks & align steering components	620	200.00	180.00 80
3	Respray scratched fuel tank		350.00	320.00 150
4	Renew damaged parts & repair affected areas		500.00	450.00 350
			<u>1,130.00</u>	<u>1,010.00</u>
Total Parts & Labours Concluded			<u>17,408.50</u>	<u>15,953.10</u>
			9779	
			20%	
Lump Sum Repair Adjustment			7823.20	<u>12,750.00</u>

L/S - \$7,800 / 4 DAYS