

ASS. REC. BY: erl

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s can't at laport
of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____
(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHCT764X /r Regn: 27 Nov 2019

Type: M.Cár / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai iCMA cc 1580Colour: yellow A/C: Insured / Std / NI / NASp. Reading: 226007 T/Radio: Insured / Std / NI / NAEng/No: KMH C85/CVC 4183710

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 1"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 23-08-21Survey held at w/s 4pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : Misc. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS SI

Photos

Other: _____

Project File No?

Project File No?

DATE: 23-Aug-21

MODEL: Hyundai Ioniq

INSURANCE: AIG ASIA CP(P)

VEHICLE NO: SHC7764Y- CityCab

MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper X After X NN	1		\$430.90
	Front Bumper Up Brkt RH X 5 nn	1		\$35.00
	Front Bumer Clips X	10	\$2.20	\$22.00
	Front Fender RH X Repair	1		\$588.80
	Front Fender Blue-Drive RH / AGC	1		\$26.60 ✓
	Front Wheel Cap RH Back	1		\$346.40 ✓
SUB TOTAL				\$1,449.70
LESS 20%				\$289.94
DISCOUNTED TOTAL				\$1,159.76
	Frt Westlake Tyre RH X nn	1		\$216.00
NETT TOTAL				\$216.00
TOTAL SPARE PARTS				\$1,375.76
Labour Charge				
Panel Beating				\$400.00
Spray Painting				\$600.00
Tuff Kote				\$40.00
Wheel Alignment				\$120.00
TOTAL LABOUR				\$1,160.00
ESTIMATE TOTAL				\$2,535.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

373

298.4

350
250
500
X ~~nn~~
60

1208.4

4 Days.

P/P

no for front panel

for 200

4pm 23/8/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: