

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008901/KQCN2**Date:** 10/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00041452100

Claimant Vehicle No : SFH6336D **Insured Vehicle No :** GBL2228K

Date of Loss: 17/08/2021 Nature of Claim: TP Claim No: SNM21D204706/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH6336D**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8137775

Reg. Date: 20/09/2017 (Man. Year: 2017) Chassis No: ZYX102051365

Colour: Metallic Pearl White Odometer: 115078 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,775.00	1,012.50	762.50	42.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	715.00	1,235.00	63.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,725.00	1,727.50	1,997.50	53.62
Approved Total (Overridden) (\$\$)		1,350.00		
Nett Amount (\$\$)	3,725.00	1,350.00	2,375.00	63.76

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 30/08/2021 Inspected At: A T Auto Consultant (HQ)
B/113 Teck Whye Lane, #05-650
Singapore 680113

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Sep 2021)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFH6336D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR RH	Cracked/Jammed	1,239.30 FL	*1,239.30 FL
2	1		*SIDE MIRROR COVER RH	Cut/Dented	110.70 FL	*110.70 FL
3	1		*BUMPER FRONT	Repair	950.00 FL	*- FL
4	1		*FENDER FRONT RH (NPA)	Repair	0.00 FL	*- FL
5	1		*DOOR FRONT RH (NPA)	Repair	0.00 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,350.00	1,350.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	575.00	337.50
Total Parts (\$\$)	1,775.00	1,012.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	500.00	200.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,000.00	450.00
3	WIRING CHARGES	New	100.00	15.00
4	RECONFIGURATION OF SIDE MIRROR 360 VIEW CAM	New	150.00	50.00
5	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	80.00	0.00
6	4 WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$)			1,950.00	715.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >