

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305484134
Date : 24-08-21
Time of Fax :

Via Fax : EMAIL
Your Insured : SMK 2184C
Date of Acc : 24.08.21

Attn: Motor Claims Department AIG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 2842 Z

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **chianglc@cdge.com.sg**
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully


For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA2842Z

24.08.21

MAKE 11/11/19

CHIANG/AIG

MODEL IONIQ G4

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER STAY LH/RH		\$138.10
10	REAR BUMPER CLIPS		\$2.20
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER LOWER COVER		\$155.00
1	BUMPER TOW COVER		\$98.80
1	ANTENNA ASSYSMART KEY		\$40.50
2	REAR NUMBER PLATE LAMP		\$85.30
1	REAR BUMPER FOG LAMP		\$201.10
	SUB TOTAL		\$2,325.45
	20.00%		\$465.09
	DISCOUNTED TOTAL		\$1,860.36
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$235.00
	Labour Charge		
	Panel Beating		\$700.00
	Spray Painting Charge		\$300.00
	Check Wiring and Lighting		\$60.00
	Tuff Kote		\$90.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,210.00
	ESTIMATE TOTAL		\$3,305.36
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			