

REPAIR ESTIMATE*

VEHICLE NO SHA2842Z

24.08.21

MAKE 11/11/19

CHIANG/AIG

MODEL IONIQ G4

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40 Xr
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 Xr ? XSVC
1	REAR BUMPER REINFORCEMENT		\$394.80 ? XSVC
1	REAR BUMPER STAY LH/RH		\$138.10 \$276.20 ? XSVC
10	REAR BUMPER CLIPS		\$2.20 \$22.00 / nec
1	REAR BUMPER CENTRE MOULDING		\$451.25 Xr ✓ DAM.
1	REAR BUMPER LOWER COVER		\$155.00 Xr ✓ Svc.
1	BUMPER TOW COVER		\$98.80 Xr Svc
1	ANTENNA ASSYSMART KEY		\$40.50 ? XSVC
2	REAR NUMBER PLATE LAMP		\$85.30 \$170.60 Xr Svc
1	REAR BUMPER FOG LAMP		\$201.10 Xr Svc
	SUB TOTAL		\$2,325.45
	20.00%		\$465.09
	DISCOUNTED TOTAL		\$1,860.36
1	Rear bumper mat		\$50.00 Xr Svc
1	REAR NUMBER PLATE W/HOLDER		\$55.00 Xr Svc
1	REAR REVERSE SENSOR		\$180.00 Xr Svc
			\$235.00
	Labour Charge		
	Panel Beating		\$700.00 350
	Spray Painting Charge		\$300.00 250
	Check Wiring and Lighting		\$60.00 30
	Tuff Kote		\$90.00 30
	Remove/refix Reverse sensor		\$60.00 30
	TOTAL LABOUR		\$1,210.00
	ESTIMATE TOTAL		\$3,305.36
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thuan 82235769 Lkh
 Thuan@lkhauto.com
 2 days wp
 24/8/21 1630
 bfr paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: