



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108043

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 19/11/2021  
Reference CC3/CTI21008908/Kea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5322Y  
Insured Veh. GBH 1227R  
Claim No. SNM21D204637/C02  
Policy No. DMCVSNW00125772000  
Accident Date 20/08/2021  
Inspection Date 23/08/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                              |                 | Ref: CC3/CTI21008908/Kea3q2<br>Date: 19/11/2021<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                 |                                                              |  |
| Insured Veh.                                                                                                                           | GBH 1227R                                                                    | Veh. Inspected  | SHD 5322Y                                                    |  |
| Policy No.                                                                                                                             | DMCVSNW00125772000                                                           | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM21D204637/C02                                                             | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                              | Assign Date     | 23/08/2021                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                 |                                                              |  |
| Make & Model                                                                                                                           | TOYOTA PRIUS (A)                                                             | c.c             | 1798                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.    | 2019                                                         |  |
| Chassis No.                                                                                                                            | JTDKB3FU603078747                                                            | Colour          | M.P.WHITE /RED                                               |  |
| Odometer                                                                                                                               | 202368 KM                                                                    | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                     | Modification    | STANDARD ALLOY RIM                                           |  |
| General                                                                                                                                | GOOD                                                                         |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                 |                                                              |  |
|                                                                                                                                        | Size                                                                         | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                                   | SAILUN          | 8 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                                   | SAILUN          | 8 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                                   | SAILUN          | 8 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                                   | SAILUN          | 8 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                              |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                              |                 |                                                              |  |
| Accident Date                                                                                                                          | 20/08/2021                                                                   | Inspection Date | 23/08/2021                                                   |  |
| Survey held at                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                              |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                              |                 | 2 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5322Y

| Qty | Description of Parts                                                                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                           |                      |                           |                   |
| 1   | COVER ,FRONT BUMPER                                                                          | MTG CRACKED          | 516.00                    | 516.00            |
| 1   | STAY SUB-ASSY ,FRONT BUMPER ,LH                                                              | SERVICEABLE          | 47.50                     | -                 |
| 1   | BRACKET ,FRONT BUMPER SIDE ,LH                                                               | DISTORTED            | 59.30                     | 59.30             |
| 1   | LAMP ASSY ,FOG, LH                                                                           | SERVICEABLE          | 951.40                    | -                 |
| 1   | FENDER SUB-ASSY ,FRONT LH                                                                    | BENT                 | 977.80                    | 977.80            |
| 1   | LINER ,FRONT FENDER ,LH                                                                      | SERVICEABLE          | 202.50                    | -                 |
| 1   | EMBLEM ,SIDE PANEL                                                                           | NECESSARY            | 54.60                     | 54.60             |
| 1   | PANEL SUB-ASSY ,FRONT DOOR ,LH                                                               | TO REPAIR SEE LABOUR | 1,300.70                  | -                 |
| 1   | WEATHERSTRIP ,FRONT DOOR ,LH                                                                 | SERVICEABLE          | 231.30                    | -                 |
| 1   | HINGE ASSY ,FRONT DOOR ,LOWER LH                                                             | TO REPAIR SEE LABOUR | 110.60                    | -                 |
| 1   | HINGE ASSY ,FRONT DOOR ,UPPER ,LH                                                            | TO REPAIR SEE LABOUR | 97.50                     | -                 |
| 1   | TAPE ,BLACK OUT ,NO.1 FRT LH                                                                 | NOT NECESSARY        | 13.30                     | -                 |
| 1   | TAPE ,BLACK OUT ,NO.2 FRT LH                                                                 | NOT NECESSARY        | 43.50                     | -                 |
| 1   | TAPE ,BLACK OUT ,NO.3 FRT LH                                                                 | NOT NECESSARY        | 26.30                     | -                 |
| 1   | MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH                                                   | SERVICEABLE          | 926.00                    | -                 |
| 1   | REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH                                                    | SERVICEABLE          | 238.30                    | -                 |
|     | LESS 25% DISCOUNT                                                                            |                      | -1,449.15                 | -401.92           |
|     |                                                                                              |                      | 4,347.45                  | 1,205.78          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                             |                      |                           |                   |
| 1   | FENDER CLIP (SN)                                                                             | NOT NECESSARY        | 65.00                     | -                 |
| 1   | FENDER LINER CLIP (SN)                                                                       | NOT NECESSARY        | 65.00                     | -                 |
| 1   | SET DOOR WEATHERSTRIP CLIP (SN)                                                              | NOT NECESSARY        | 65.00                     | -                 |
| 1   | FRT DOOR STICKER TRANSCAB (SN)                                                               | NOT NECESSARY        | 100.00                    | -                 |
| 1   | FRT BUMPER CLIP (SN)                                                                         | NECESSARY            | 65.00                     | 50.00             |
|     |                                                                                              |                      | 360.00                    | 50.00             |
|     | <b><u>LABOUR</u></b>                                                                         |                      |                           |                   |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR. | NOT NECESSARY        | 380.00                    | -                 |

Report Ref No. CC3/CTI21008908/Kea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                         | Description of Parts                                                                                                                                                                                                                                         | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                             | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,FRONT DOOR ,LH ,HINGE ASSY ,FRONT DOOR ,LOWER LH AND HINGE ASSY ,FRONT DOOR ,UPPER ,LH . |           | 1,400.00                  | 300.00            |
|                             | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .                                                                                                                                                                                                           |           | 1,400.00                  | 440.00            |
|                             | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .                                                                                                                                                                                                 |           | 240.00                    | 30.00             |
|                             | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                                                                                      |           | 170.00                    | 15.00             |
|                             |                                                                                                                                                                                                                                                              |           | 3,590.00                  | 785.00            |
| GRAND TOTAL                 |                                                                                                                                                                                                                                                              |           | 8,297.45                  | 2,040.78          |
| RECOMMENDED COST OF REPAIRS |                                                                                                                                                                                                                                                              |           |                           | 2,040.78          |

Report Ref No. CC3/CTI21008908/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5322Y

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHD 5322Y**

**RE-INSPECTION**

