

ASS. REC. BY:

REF: C72/ 21008908/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: S14D 53227 Yr Regn: 01, 1P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.C. 179PColour: n.p. white/Red A/C: Insured / Std / Nil / NASp. Reading: 202368 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTDBK3FU 603 078747Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sailun

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/12/21D.O.I. 23/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Fees

☐ : Tech Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5322Y*Not Authorized
Returning B& paint***AAD2108-****22040.78**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

23 AUG 2021**SHD5322Y**

JTDKB3FU603078747

TOYOTA

PRIUS

20/08/2021

CHINA

11/01/2019

PART		LIST	
1	COVER, FRONT BUMPER	\$	<i>mtgum</i> 516.00 ✓
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	<i>sn</i> 47.50 X
1	BRACKET, FRONT BUMPER SIDE, LH	\$	<i>mtgum</i> 59.30 ✓
1	LAMP ASSY, FOG, LH	\$	<i>sn</i> 951.40 X
1	FENDER SUB-ASSY, FRONT LH	\$	<i>sn</i> 977.80 ✓
1	LINER, FRONT FENDER, LH	\$	<i>sn</i> 202.50 X
1	EMBLEM, SIDE PANEL	\$	<i>mtgum</i> 54.60 ✓
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	<i>mtgum</i> 1,300.70
1	WEATHERSTRIP, FRONT DOOR, LH	\$	<i>sn</i> 231.30
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	<i>mtgum</i> 110.60
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	<i>mtgum</i> 97.50
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	<i>mtgum</i> 13.30
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	<i>mtgum</i> 43.50
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	<i>mtgum</i> 26.30
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	<i>sn</i> 926.00
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	<i>sn</i> 238.30
TOTAL		\$	5,796.60
25%		\$	1,449.15
		\$	4,347.45

Special Nett

1	FENDER CLIP	\$	<i>mtgum</i> 65.00 X
1	FENDER LINDER CLIP	\$	<i>mtgum</i> 65.00 X
1SET	DOOR WEATHERSTRIP CLIP	\$	<i>mtgum</i> 65.00 X
1	FRT DOOR STICKER TRANSCAB	\$	<i>mtgum</i> 100.00 X
1	FRT BUMPER CLIP	\$	<i>mtgum</i> 65.00 <i>50.00</i>

Trans-cab Auto Services Pte Ltd

AAD2108-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5322Y

TOTAL

\$	360.00
----	--------

TOTAL PARTS	\$	4,707.45
--------------------	----	-----------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>na</i>	380.00	X
----	-----------	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		1,400.00	<i>300</i>
----	--	----------	------------

Putty And Spray Painting Of The Affected Portion.

\$		1,400.00	<i>440</i>
----	--	----------	------------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$		240.00	<i>30</i>
----	--	--------	-----------

To Check Electrical Lighting Concerned.

\$		170.00	<i>15</i>
----	--	--------	-----------

TOTAL	\$	3,590.00
--------------	----	-----------------

Over All Total	\$	8,297.45
-----------------------	----	-----------------

(PART-BY-PART) Repair Days*20 days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: