



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

23/08/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 17/08/2021

Estimated repair cost for vehicle no : SJQ8955J HONDA CIVIC

CHASSIS:

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Debond</i>	\$648.30	✓ \$648.30
2	1	REAR BUMPER SIDE RETAINER RH <i>xler</i>	\$56.40	28 \$56.40
3	1	REAR FENDER RH <i>Repair</i>	\$1,452.30	X \$1,452.30
4	1	REAR FENDER INNER SHIELD RH <i>torn</i>	\$158.40	✓ \$158.40
5	1	REAR FENDER AIR VENT RH <i>NE m</i>	\$62.50	X \$62.50
6	1	REAR FENDER MUDFLAP RH <i>NE m</i>	\$52.60	X \$52.60
7	1	RH REAR TAILLAMP <i>NE m</i>	\$557.40	X \$557.40
8	1	RH REAR TAILLAMP LOWER BRACKET <i>NE m</i>	\$31.40	X \$31.40
9	1	RH REAR LOWER ARM <i>Bent</i>	\$654.50	✓ \$654.50 <i>325</i>
10	1	RH REAR SHOCK ABSORBER <i>NE m</i>	\$389.60	X \$389.60
11	1	RH REAR UPPER ARM <i>NE m</i>	\$342.50	X \$342.50
12	1	RH REAR KNUCKLER ARM BEARING <i>Debond</i>	\$215.60	✓ \$215.60
13	1	REAR WINDSCREEN GLASS MOULDING <i>NE m</i>	\$154.60	X \$154.60

1375.30

1100.24

TOTAL : \$4,776.10
LESS 20 % \$955.22
SUB-TOTAL : \$3,820.88

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>New</i>	\$80.00	30 \$80.00
2	1	REAR TAILLAMP CLIPS RH <i>NE m</i>	\$20.00	X \$20.00
3	1	REAR BUMPER LOWER SPOILER <i>Debond</i>	\$850.00	800 \$850.00
4	1	RH REAR SPORT RIM <i>lit</i>	\$750.00	480 \$750.00
5	1	RH REAR TYRE <i>NE m</i>	\$280.00	X \$280.00
6	1	REAR WINDSCREEN GLASS SEALANT <i>NE m</i>	\$100.00	X \$100.00
8	1	REAR BUMPER LOWER SPOILER SEALANT <i>NE m</i>	\$60.00	40 \$60.00
9	1	REAR BUMPER LOWER SPOILER CLIPS <i>NE m</i>	\$50.00	X \$50.00

1380

TOTAL: \$2,190.00

TOTAL PARTS \$6,010.88

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 TO CONDUCT WHEEL ALIGNMENT
- 6 LABOUR FOR REMOVE & TRANSFER REAR WINDSCREEN GLASS
- 7 LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY / ROOF LINING

4W ~~\$1,200.00~~
600 ~~\$1,000.00~~
30 ~~\$80.00~~
50 ~~\$300.00~~
80 ~~\$150.00~~
+ \$150.00
+ \$250.00

1160

Subtotal :- \$3,130.00

Total:- \$9,140.88

total: 3610.24

L/S: 2.9K.

04 Days.

2.9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: