

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

INDIA

Owner : Muhammad Firdauz bin Abdul
bakar (87495042)

Accident Date : 08-Aug-21

Vehicle No : FX8596Y

Vehicle Model : Honda CB400
M

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender Cne 165	\$ 220.00 ✓
1	Headlamp 17	\$ 528.00 X
1	Headlamp bracket 17	\$ 88.00 X
1	Headlamp rear bracket 17	\$ 105.00 X
2	Fork inner tubes 17	\$ 1,020.00 X
2	Fork outer tubes SCL	\$ 1,040.00 X
1	Fork under bracket 17	\$ 385.00 X
1	Fork upper bracket 17	\$ 285.00 X
2	Front brake discs o/s Bent n/san 545	\$ 1,120.00 1PC
1	Front rim shaft 17	\$ 68.00 X
1	Front sport rim R	\$ 1,100.00 X
1	Meter casing only cur 8365	\$ 1,880.00 ✓
1	Handle-bar 17	\$ 580.00 X
1	Handle-bar end (1 set) 17	\$ 120.00 X
1	Hand-grip (1 set) 17	\$ 110.00 X
2	Side mirrors n/s cur o/san 110	\$ 220.00 1PC
1	Clutch lever cur 122	\$ 358.00 —
1	Front signals (1 set) 17	\$ 480.00 X
1	Fuel tank 17	\$ 1,318.00 X
2	Front footrests n/s cur o/san 68	\$ 150.00 1PC
2	Front footrest bracket 17	\$ 490.00 X
1	Gear pedal SCL	\$ 180.00 X
1	Rear footrest cur	\$ 95.00 —
1	Side boards - L/H R	\$ 280.00 +
1	Site stand dyed 98	\$ 110.00 —
1	Rear tailboard cne 325	\$ 380.00 —
1	Rear taillamp cur 285	\$ 480.00 —
		\$ 13,190.00
	Less 10%	\$ 1,319.00
		\$ 11,871.00

Not Authorized
data records
24/8/21
2/5/2100/
whenever attention

Less 10%

32y.

2178
102
1960.2

H514070y

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Muhammad Firdauz bin Abdul
bakar (87495042)

Accident Date : 08-Aug-21

Vehicle No : FX8596Y

Vehicle Model : Honda CB400
M

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>kerf</i>	\$	38.00	<i>10</i>
2	Fork oils <i>X NN</i>	\$	30.00	<i>X</i>
2	Fork oil seals <i>X NN</i>	\$	56.00	<i>X</i>
1	Steering cone (1 set) <i>X NN</i>	\$	150.00	<i>X</i>
1	Engine slider (1 set) <i>647</i>	<i>150</i> \$	580.00	<i>✓</i>
1	E.R.P. IU (LOD) <i>117</i>	\$	155.80	<i>X</i>
		\$	1,009.80	

S/No. Labour

1	To provide towing service - 2 trips (LOD)	\$	100.00	<i>50</i>
2	To check wiring and reset headlamp focusing	\$	<i>11</i> 80.00	<i>X</i>
3	To respray painting	\$	600.00	<i>200</i>
4	To repair body frame	\$	<i>11</i> 500.00	<i>X</i>
5	To provide labour	\$	600.00	<i>280</i>
		\$	1,880.00	

Grand Total

\$ 14,760.80

Singapore Dollars: Fourteen Thousand Seven Hundred Sixty and Cent: Eighty only

2650.2

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: