



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref: CS/TP21008912/Uvf3e2	
BLK 1 KAKI BUKIT AVE 6			Date: 28/09/2021	
#01-28/51/53/55(MAIN OFFICE)SINGAPORE				
417883				
ON BEHALF OF ONG CHEE YONG			Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected		SJZ 629G
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		24/08/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 3 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JM6BL10Z1A0146682	Colour	WHITE	
Odometer	285156 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/08/2021	Inspection Date	24/08/2021	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	