



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: TEE CHEE WAH		Ref: CS3/AIG21007145/Eqf3e2-1 Date: 07/09/2021 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 6271D	Veh. Inspected	SME 7746E
Policy No.	2070095895	Coverage (\$)	0.00
Claim No.	9016542657SG	Excess (\$)	0.00
Assign From	TEE CHEE WAH	Assign Date	24/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MR053REH604591679	Colour	GREY
Odometer	56241 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	4 mm
L/H Front Tyre	205/55 R16	DUNLOP	4 mm
R/H Rear Tyre	205/55 R16	DUNLOP	4 mm
L/H Rear Tyre	205/55 R16	DUNLOP	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/06/2021	Inspection Date	30/06/2021
Survey held at	TIAN SIANG MOTOR 27-A JURONG PORT ROAD #01-19, JURONG INDUSTRIAL ESTATE SINGAPORE 619101		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	