



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 21013-06/AY / 2021**
Date of Report : **19 Jul 2021**

Teo Teck Wah
Blk 625 Senja Road
#23-146
Singapore 670625

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 26 Jun 2021

Workshop Address : Tian Siang Motor
27-A Jurong Port Road
Blk 5, Jurong Industrial Estate, #01-18
Singapore 619101

As per your instruction dated **30 Jun 2021** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SME 7746 E**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SME 7746 E	Engine No	: 1ZR0C39998
Model	: Toyota Corolla Altis	Mileage	: 56241
Year / Capacity	: 2018/1598	Colour	: Grey
Chassis No	: MR053REH604591679		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	: 205/55 R16	Dunlop	4.00 mm	Sport
REAR O/S	: 205/55 R16	Dunlop	4.00 mm	Sport
FRONT N/S	: 205/55 R16	Dunlop	4.00 mm	Sport
REAR N/S	: 205/55 R16	Dunlop	4.00 mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 5 working days to complete.
5. Enclosed number of photograph : 97 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SME 7746 E**
 Report No: **TP/ 21013-06/AY / 2021**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
2	Front headlamps	Damage	\$ 4975.60	\$ 4975.60 4446-
1	Front grille	Damage	\$ 712.10	\$ 712.10 382-
1	Front grille logo	Intact	\$ 57.90	\$
1	Front grille top cover	Intact	\$ 80.70	\$
1	Front bumper	Damage	\$ 531.10	\$ 531.10 ✓
1	Front bumper inner sponge	Damage	\$ 111.80	\$ 111.80 ✓
1	Front bumper fog lamp	Intact	\$ 224.60	\$
1	Front bumper fog lamp cover	Intact	\$ 105.80	\$
1	Front bumper lower grille	Damage	\$ 169.60	\$ 169.60 ✓
1	Front bumper reinforcement	Repair	\$ 399.50	\$
			<u>\$ 7368.70</u>	<u>\$ 6500.20</u>
	Discount	25.0%	\$ 1842.18	\$ 1625.05
			<u>\$ 5526.52</u>	<u>\$ 4875.15</u>
<u>Special Nett Items</u>				
1	Front number plate c/w frame	Damage	\$ 80.00	\$ 55.00 45-
			<u>\$ 80.00</u>	<u>\$ 55.00</u>

Spare Parts Total \$ 5606.52 \$ 4930.15


Vehicle No: **SME 7746 E**
Report No: **TP/ 21013-06/AY / 2021**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 5606.52	\$ 4930.15
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 30 ✓
2	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 660.00 300 ✓
3	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 660.00 300 ✓
4	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 30.00 ✓
Total		<u>\$ 7556.52</u>	<u>\$ 6320.15</u>

Recommended PART BY PART Repair Amount of: \$ **6320.15**

SDLS: SIX THOUSAND THREE HUNDRED TWENTY AND CENTS FIFTEEN ONLY


Qualified Appraiser

Part by Part
3 days





