

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WINTER AIR PTE LTD
7 MANDAI LINK #07-39 MANDAI
CONNECTION
SINGAPORE 728653

Contact : 90046608, 89056159

TP Budget Direct.
Veron.

ESTIMATE

Repair Code : CLM15293
Date in : 24/08/2021
Vehicle Num. : GBE3429C
Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL
Chassis/Eng# : JTFHT02P500181186/1KD2546479

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	695.90	✓ 695.90
REAR BUMPER LOWER BRACKET <i>Bent</i>	4	30.00	✓ 120.00
REAR BUMPER SIDE RETAINER L/R <i>Cracked</i>	2	60.87	✓ 121.74
REAR END PANEL (INNER) <i>Dented</i>	1	859.50	<i>685</i> 859.50
REAR END PANEL (OUTER) <i>Dented</i>	1	388.27	✓ 388.27
REAR LH TAILLAMP INNER PANEL <i>Dented</i>	1	571.74	✓ 571.74
REAR SPARE TYRE CARRIAGE <i>Bent</i>	1	398.80	✓ 398.80
REAR SPARE TYRE CARRIAGE BRACKET <i>new</i>	1	178.10	+ 178.10
REAR SPARE TYRE CARRIAGE BRACKET SCREW <i>Bent</i>	1	121.10	✓ 121.10
REAR TAILGATE <i>Dented</i>	1	1890.54	<i>1735</i> 1890.54
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	85.87	✓ 85.87
REAR TAILGATE HINGES L/R <i>new</i>	2	96.57	+ 193.14
REAR TAILGATE INNER LOCK CONTROL ASSY <i>new</i>	1	290.95	+ 290.95
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	48.70	+ 97.40
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	325.00	+ 325.00
REAR TAILGATE LOCK STRIKER <i>new</i>	1	68.57	+ 68.57
REAR TAILGATE MECHANISM LOCK <i>Dented</i>	1	235.00	✓ 235.00
REAR TAILGATE OUTER GARNISH HANDLE <i>new</i>	1	137.70	+ 137.70

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WINTER AIR PTE LTD
7 MANDAI LINK #07-39 MANDAI
CONNECTION
SINGAPORE 728653

Contact : 90046608, 89056159

ESTIMATE

Repair Code : CLM15293

Date in : 24/08/2021

Vehicle Num. : GBE3429C

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02P500181186/1KD2546479

REAR TAILGATE WEATHER STRIP <i>at</i>	1	395.90	✓	395.90
REAR TAILLAMP L/R <i>changed</i>	2	395.80	✓	791.60
REAR TAILLAMP LOWER GARNISH L/R <i>Del'd</i>	2	88.63	✓	177.26
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R <i>new changed</i>	2	50.84	✓	101.68
Subtotal before discount				8,245.76
Percentage discount 25%				2,061.44
Sub-total 1				6,184.32
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR <i>Dem'd</i>	1	280.00	200	280.00
REAR TAILGATE '70KM' STICKER <i>3 per</i>	1	25.00	10	25.00
REAR TAILGATE '8PC' STICKER	1	25.00	10	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	350	50.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	+	25.00
REAR TAILGATE OUTER HANDLE CLIPS - SET <i>new</i>	1	30.00	+	30.00
REAR TAILGATE WINDSCREEN SEAL <i>new</i>	1	80.00	40	80.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	40	80.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	25.00	20	50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WINTER AIR PTE LTD
7 MANDAI LINK #07-39 MANDAI
CONNECTION
SINGAPORE 728653

Contact : 90046608, 89056159

ESTIMATE

Repair Code : CLM15293

Date in : 24/08/2021

Vehicle Num. : GBE3429C

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02P500181186/1KD2546479

Subtotal before discount	695.00
--------------------------	--------

Percentage discount 0%	0.00
------------------------	------

Sub-total 2	695.00
--------------------	--------

Parts-total	6,879.32
--------------------	-----------------

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,710.00
---------------------	-----------------

Parts & Labour Total	9,589.32
---------------------------------	-----------------

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 3

Adrian L
2/c 26/08/21
068 pags.
total: 7303.64
2/c: 5.8K ✓