

ASS. REC. BY:

REF:

AIG/ 210089181K3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S11D 81A Yr Regn: 07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: PENALT Contudo c.c. 1995Colour M. white 1A A/C: Insured / Std / NI / NASp. Reading 487883 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFI ABL 15AUC 283395Gen. Cond: Good Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: M11S Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front

Rear

R/Bal. S mmR/Bal. S mmL/Bal. S mmL/Bal. S mmD.O.A. 23/8/21D.O.I. 24/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/8 21:00 @ 11501 Contino

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Fees

☐ : Tech Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD81A**AAD2108-***Not Notified
11 Pm \$1150/h*

Vehicle No.:

Chassis No.:

Vehicle Make:

24 AUG 2021

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD81A

VF1ABL15AUC283395

RENAULT

LATITUDE

23/08/2021

AIG

24/07/2017

- | | PART |
|---|-----------------------------------|
| 1 | BUMPER COVER REAR |
| 1 | BUMPER LOWER REAR |
| 1 | BUMPER BRACKET CTR REAR |
| 1 | BUMPER BRACKET SIDE RH REAR |
| 1 | BUMPER RETAINER RH REAR |
| 1 | BUMPER BEAM REAR |
| 1 | OUTER PANEL REAR |
| 1 | OUTER PANEL REAR (End Panel) TRIM |

LIST

\$	<i>Bu/nd</i>	561.70	✓
\$	<i>nd/ln</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	547.80	X
\$	<i>SL</i>	745.80	X
\$	<i>SL</i>	404.56	X

TOTAL \$ 2,911.76**10% \$ 291.18****\$ 2,620.58****Special Nett**

- | | |
|---|------------------------|
| 1 | REVERSE SENSOR |
| 1 | REAR BUMPER CLIP |
| 2 | REAR LOWER BUMPER CLIP |

\$	<i>SL</i>	700.00	X
\$	<i>SL</i>	65.00	✓
\$	<i>SL</i>	65.00	✓

TOTAL \$ 830.00**TOTAL PARTS \$ 3,450.58****LABOUR**

To transfer of door fittings, attachment and perform water seepage test.

\$ *nn* 300.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ *nn* 300.00 X

Trans-cab Auto Services Pte Ltd

AAD2108-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD81A

To remove and refit interior fittings, trimings,
garnish, fittings and others, to enable repair. \$ *nn* 380.00 X

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same \$ 1,400.00 *2001*

To rust-proofing and apply undercoat of the affected
areas. \$ *nn* 240.00 X

Putty and spray painting of the affected portion. \$ 1,400.00 *2201*

To transfer of tire, rim and on wheel balancing. \$ *nn* 170.00 X

To Check Electrical Lighting Concerned. \$ *nn* 170.00 X

TOTAL \$ **4,580.00**

Over All Total \$ **8,030.58**

LUMP SUM (REPAIR DAY) **~~20~~ DAYS**

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD81A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Aug 2021
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003114
Chassis No.:	VF1ABL15AUC283395
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$18,878.00
Total Rebate Amount:	\$33,876.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Aug 2021

OK