

Spark Car Care
 ComfortDelgro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Finalization Form

Bil : CHINA TAIPING **Vehicle Number** : SMY3746B
Attn to : KENNETH (LKK) **Type Of Claim** : TP

<p>A. Spare parts \$ <u>8,574.40</u></p> <p>B. Supplementary \$ <u>921.30</u></p> <p>C. Nett Price \$ <u>-</u></p> <p>D. Supp Nett Price \$ <u>-</u></p> <p>E. S/Nett \$ <u>256.00</u></p>	<p>F. Total Parts \$ <u>7,852.56</u></p> <p>G. Total Labour \$ <u>2,390.00</u></p> <p>H. Total Repair \$ <u>10,242.56</u></p> <p>I. Excess _____</p> <p>P/P Total \$ <u>10,242.56</u> ✓ d/c</p>
--	---

Total Spare Parts Price	\$ 9,495.70
Cost plus / List Down 20%	\$ 1,899.14
Total	\$ 7,596.56

Total Nett Price	\$ -
Nett Price Less _____	\$ -
Total	-

Lump Sum Less _____ \$ -

Lump Sum Rounding _____

Total Finalized **\$ 10,242.56**

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day : _____
Date Survey : _____	LOU/ Day : _____
Date Out : _____	Total LOU : _____
Sat/Sun/Ph. : _____	Rental/Day : _____
Authorized Repair Day : _____	Total Rental : _____
Submitted By / Date : _____	Confirmed By / Date : _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Page 1

Spare Parts

Vehicle No : SMY3746B Case Owner : 0
Make & Model : MAZDA3 M-HYBRID Year Manufacture : 2021
Chassis No : JM6BP2SAAM1107114 Engine No : 0
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER <i>997.40</i>	1	<i>12</i>	\$ 997.40			<input checked="" type="checkbox"/>
	REAR BUMPER REINFORCEMENT <i>K</i>	1		<i>541.70</i>			<input checked="" type="checkbox"/>
3	REAR BUMPER TOW COVER LH	1	<i>mi</i>	\$ 12.80			<input checked="" type="checkbox"/>
4	REAR BUMPER REFLECTOR LH	1	<i>per</i>	\$ 36.00			<input checked="" type="checkbox"/>
5	REAR BUMPER SIDE RETAINER LH	1	<i>cm</i>	\$ 33.20			<input checked="" type="checkbox"/>
6	REAR BUMPER CLIPS	10	<i>m</i>	\$ 30.00			<input checked="" type="checkbox"/>
7	REAR BUMPER SENSOR OUTER LH	1	<i>in</i>	<i>190</i>			<input checked="" type="checkbox"/>
8	TAILLAMP LH <i>538.40</i>	1	<i>cm</i>	\$ 538.40			<input checked="" type="checkbox"/>
9	TAILLAMP SIDE COVER LH	1	<i>di</i>	\$ 14.60			<input checked="" type="checkbox"/>
10	REAR WINDSCREEN MOULDING	1	<i>m</i>	\$ 149.90			<input checked="" type="checkbox"/>
11	SEALANT	1	<i>m</i>			\$ 40.00	<input checked="" type="checkbox"/>
12	INNER SEAL	1				\$ 20.00	<input checked="" type="checkbox"/>
13	LH REAR FENDER <i>1643.60</i>	1	<i>B</i>	\$ 1,643.60			<input checked="" type="checkbox"/>
14	LH REAR FENDER INNER SHIELD	1	<i>di</i>	\$ 172.70			<input checked="" type="checkbox"/>
15	LH REAR FENDER INNER SHIELD CLIPS	10	<i>m</i>	\$ 19.00			<input checked="" type="checkbox"/>
16	LH REAR FENDER INNER TRIM BORAD	1	<i>in</i>	<i>641.90</i>			<input checked="" type="checkbox"/>
17	LH REAR LOWER ARM <i>nsp</i>	1	<i>in</i>				<input checked="" type="checkbox"/>
18	LH REAR KNUCKLE ARM <i>in</i>	1	<i>in</i>				<input checked="" type="checkbox"/>
19	LH REAR KNUCKLE BEARING WITH HUB	1	<i>B</i>	\$ 437.60			<input checked="" type="checkbox"/>
20	LH REAR SHOCK ABSORBER	1	<i>B</i>	\$ 322.20			<input checked="" type="checkbox"/>
21	LH REAR ABS SENSOR	1	<i>in</i>				<input checked="" type="checkbox"/>
22	LH REAR RIM '16	1	<i>in</i>	\$ 890.90			<input checked="" type="checkbox"/>
23	TYRE YOKOHAMA BLUEARTH GT 205/60 R16	1	<i>in</i>	<i>280</i>		\$ 196.00	<i>Fobin</i>
24	REAR EXHAUST PIPE <i>1486.80</i>	1	<i>B</i>	\$ 1,486.80			<input checked="" type="checkbox"/>
25	REAR AXLE <i>1789.30</i>	0	<i>B</i>	\$ 1,789.30			<input checked="" type="checkbox"/>
26	0	0					
27	0	0					
28	0	0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

05/10/2021

8:49 AM

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. :	<u>SMY3746B</u>	Case Owner :	<u>0</u>
Make & Model :	<u>MAZDA3 M-HYBRID</u>	Year of Manufacture :	<u>2021</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SMY3746B Case Owner : 0
Make & Model : MAZDA3 M-HYBRID Year Manufacture : 2021
Chassis No : JM6BP2SAAM1107114 Engine No : 0
Sales Order : 0 Supplier : 0
Order By : _____ Type of Claim : TP

No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	TAILLAMP PANEL LH	1	<i>By</i>	\$ 166.50			<i>✓</i>
2	LH REAR FENDER AIR GRILLE	1	<i>nd</i>	\$ 43.10			<i>✓</i>
3	LH REAR FENDER AIR GRILLE PANEL	1	<i>nd</i>	\$ 107.60			<i>✓</i>
4	LH REAR FENDER INNER SHIELD	1	<i>cm</i>	\$ 83.50			<i>✓</i>
5	REAR BUMPER BRACKET LH	1	<i>nd</i>	\$ 33.20			<i>✓</i>
6	REAR AXLE LH COVER	1	<i>nd</i>	\$ 46.70			<i>✓</i>
7	FUEL LIP COVER	1	<i>nd</i>	\$ 440.70			<i>✓</i>
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care