

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF761K**AAD2108-***Not Notarised
L/Rp @ 11,550/-*

Vehicle No.:

Chassis No.:

24 AUG 2021

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF761K

VF1ABL15AUC283336

RENAULT

LATITUDE

23/08/2021

CHINA

30/06/2016

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel)TRIM
- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER UNDERTRAY FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 BUMPER BEAM FRT
- 1 TOW COVER FRT
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE BADGE 'RENAULT'
- 1 RADIATOR GRILLE FRAME

*Rear***LIST**

\$	<i>Bu</i>	561.70	—
\$	<i>Paint</i>	411.90	—
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>R</i>	547.80	X
\$	<i>R</i>	114.50	X
\$	<i>R</i>	114.50	X
\$	<i>R</i>	745.80	X
\$	<i>SL</i>	404.56	X
\$	<i>B/L/T</i>	747.20	✓
\$	<i>DI</i>	344.70	✓
\$	<i>CM</i>	394.68	✓
\$	<i>SL</i>	101.40	X
\$	<i>SL</i>	10.70	X
\$	<i>DI</i>	101.40	✓
\$	<i>SL</i>	10.70	X
\$	<i>CM</i>	292.50	✓
\$	<i>DI</i>	147.00	✓
\$	<i>SL</i>	207.21	X
\$	<i>DI</i>	207.21	✓
\$	<i>R</i>	663.70	✓
\$	<i>mi</i>	60.90	✓
\$	<i>CM</i>	969.90	✓
\$	<i>SL</i>	225.36	✓
\$	<i>CM</i>	686.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2108-**SHF761K**

1	FRAME FULL SUPPORT PANEL	\$	Bu 592.70	✓
1	FRAME FULL SUPPORT BRACKET	\$	B 41.60	✓
1	FRONT BRACE PANEL	\$	B 177.22	✓
1	HORN	\$	Pl 449.90	x
1	HORN BRACKET	\$	R 21.90	x
1	HEADLAMP LH	\$	CR 743.60	✓
1	HEADLAMP RH	\$	CR 743.60	✓
1	HEADLAMP PANEL FRT LH	\$	R 128.30	x
1	HEADLAMP PANEL FRT RH	\$	B 128.30	✓
1	BONNET	\$	Bu 1,312.70	✓
1	BONNET INSULATOR	\$	Pl 294.30	x
1	BONNET STRUT LH	\$	Pl 53.30	x
1	BONNET STRUT RH	\$	Pl 53.30	x
1	BONNET HINGE LH	\$	Dir 237.40	✓
1	BONNET HINGE RH	\$	Dir 237.40	✓
1	BONNET LOCK	\$	B 152.80	✓
1	FENDER PANEL FRT RH	\$	B 437.10	✓
1	FENDER PANEL FRT LH	\$	R 437.10	x
1	WHEELARCH FRT LH	\$	Pl 191.40	x
1	FENDER BRACKET LOWER LH	\$	Pl 11.80	x
1	FENDER INSULATOR LH	\$	Pl 66.30	x
1	FENDER BRACKET FRT LH	\$	R 106.40	x
1	WHEELARCH FRT RH	\$	Pl 191.40	✓
1	FENDER BRACKET LOWER RH	\$	Pl 11.80	x
1	FENDER INSULATOR RH	\$	Pl 66.30	x
1	FENDER BRACKET FRT RH	\$	R 106.40	x
1	WIPER RESERVOIR	\$	Pl 179.60	x
1	WIPER RESERVOIR NECK	\$	Pl 29.30	x
1	WIPER RESERVOIR MOTOR	\$	Pl 82.60	x
1	AIR CLEANER LOWER	\$	Pl 271.26	?
1	AIR CLEANER HOSE	\$	Pl 175.85	?
1	BASE BATTERY TRAY	\$	Pl 363.40	?
1	AIR CLEANER BOX	\$	Pl 464.20	?
1	A/C HEATER VALVE	\$	Pl 484.50	?
1	SUBFRAME OUTER FRT	\$	Pl 1,094.20	?
1	SUBFRAME BRACKET OUTER LH	\$	Pl 49.00	?
1	SUBFRAME BRACKET OUTER RH	\$	Pl 49.00	?
1	ENGINE UNDERTRAY	\$	Pl 583.10	x

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2108-**SHF761K**

1 A/C CONDENSER	\$	Bz	1,537.80	✓
1 A/C CONDENSER GARNISH LH UPPER	\$	Sm	57.30	X
1 A/C CONDENSER GARNISH RH UPPER	\$	Sm	56.70	X
1 A/C CONDENSER GARNISH LH	\$	Sm	67.90	X
1 A/C CONDENSER GARNISH RH	\$	Sm	67.70	X
1 RADIATOR	\$	Bz	871.20	✓
2 RADIATOR STUD UPPER	\$	Sm	11.10	X
2 RADIATOR BUSH UPPER	\$	Sm	11.10	X
2 RADIATOR MTG LOWER	\$	Sm	30.10	X
1 RADIATOR FAN COWLING	\$	Sm	417.00	X
1 RADIATOR FAN MOTOR LH	\$	Sm	826.70	X
1 RADIATOR FAN MOTOR RH	\$	Sm	821.20	X
1 SUBFRAME INNER FRT	\$	Sm	2,284.80	X
1 SUBFRAME SUPPORT INNER	\$	Sm	69.50	X
1 SUBFRAME BRACKET INNER FRT LH	\$	R	101.00	X
1 SUBFRAME BRACKET INNER FRT RH	\$	R	101.00	X
	\$		26,598.75	
10%	\$		2,659.88	
	\$		23,938.88	

Specical Nett

1SET PARKING AID	\$	Sm	700.00	X
1SET REAR BUMPER CLIP	\$	nn	66.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET BONNET LOCK NUT	\$	Sm	60.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
1 BUMPER CLIP FRT	\$	nn	85.00	Obser
1 BUMPER RETAINER CLIP FRT	\$	nn	70.00	X
1 BUMPER GRILLE LOWER CLIP	\$	nn	70.00	X
1 BUMPER FOG LAMP GRILLE CLIP	\$	nn	65.00	X
1 LICENSE PLATE WITH HOLDER FRT	\$	Bz	120.00	455a
1 BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	X
1SET RADIATOR GRILLE SCREW	\$	nn	16.00	X
1SET BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2108-

SHF761K

1SET FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2 FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2 FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
6 BONNET INSULATOR CLIP L70Y	\$	7.30	X
2 BONNET CABLE CLIP L70Y	\$	6.31	X
2 BONNET CABLE COVER SCREW L70Y	\$	10.85	X
TOTAL	\$	1,634.97	
TOTAL PARTS	\$	25,573.85	

LABOUR

Putty And Spray Painting Of The Affected Portion.	<i>R 81100</i> <i>Rev \$8226</i>	3,000.00	<i>13201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	<i>R 86001</i> <i>Rev \$82001</i>	6,000.00	<i>8001</i>
To Rust-Proofing Of The Affected Areas. <i>R</i>	\$	170.00	<i>901</i>
To reinstall rear bumper parking sensor. <i>R</i>	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test. <i>R</i>	\$	170.00	<i>X</i>
To repair and realign rear exhaust pipe. <i>R</i>	\$	170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. <i>R</i>	\$	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test. <i>R</i>	\$	170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test. <i>R</i>	\$	170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF761K**AAD2108-**

To check steering geometry and computer wheel alignment *F* \$ *na* 220.00 *X*

To Check Electrical Lighting Concerned. *F* \$ 170.00 *201*

TOTAL \$ 10,580.00

Over All Total \$ 60,092.72

(LUMP SUM)

Repair Days

20 DAYS

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: