



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 25/08/2021

Attn: The Motor Claims Department
Your Insured Vehicle - GBF 8436 T

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

Tel: (65) 6223 9433

Fax: (65) 6224 3903

Fax :65 6223 4190

DDI: (65) 6496 9032

Email: sreyas.kotcherlakota@eqinsurance.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimated Repair Bill for VEHICLE No. GBD9869G & GBF 8436 T on 20/08/2021 at 08:20

1pc	Rear Boot Cover	DenAd	3011.50	\$ 1,816.70	Nett ✓
1pc	Rear Boot Cover Inner Lock	new		\$ 287.10	Nett ✗
1pc	Rear Boot Cover Rubber	new	2710.71	\$ 155.00	Nett ✗
1pc	Rear Boot Cover Logo	Free		\$ 64.70	Nett ✓
1pc	Rear Boot Cover NV350 Logo		S.N: 20.	\$ 64.70	Nett ✓
1pc	Rear Boot Cover Moulding	new		\$ 535.70	Nett ✗
2pcs	Rear Lamp	Replaced	2 \$277.40	\$ 554.80	Nett 277.40
1pc	Rear Bumper	Disbld		\$ 677.00	Nett ✓
2pcs	Rear Bumper Side Retainer	new	2 \$ 40.70	\$ 81.40	Nett ✓
1pc	Rear Bumper Bracket	new		\$ 171.90	Nett ✗
10pcs	Rear Bumper Clips	new	10 \$ 12.50	\$ 125.00	Nett 30
1pc	Rear Lamp Inner Panel RH	Rejis		\$ 490.10	Nett ✗
1pc	70km Sticker	Free		\$ 35.00	Nett 10 (SW)
1pc	8pax Sticker			\$ 35.00	Nett 10 (SW)
				\$ 5,094.10	
LESS 10%				\$ 509.41	
				\$ 4,584.69	
1pc	Reverse Sensor	2000	260	\$ 350.00	S/Nett 200
1pc	Wimdscreen Sealant	new		\$ 85.00	S/Nett 60
				\$ 5,019.69	
To dismantl & replace damage parts, panel beat where necessary				\$ 890.00	800
To putty, apply primer & spray paint on the affected portion.				\$ 950.00	900
To remove Diesel Tank				\$ 250.00	1910
To remove and refix windscreen				\$ 150.00	120
To check wiring functions.				\$ 90.00	50
To remove upholstery.				\$ 80.00	40
				\$ 7,429.69	

Total: 4900.71
H/S: 39K.

Adam Lij
H/S 26/08/21
05 Days