

ASS. REC BY: *Marica*

REF:

CS/SMR21008925/Uuf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLM 9336L*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame /

Body Structure affected due to collision.

Date / Time

Action / Instruction

27/9/12 1/5 @ 1500 confirmed with AH Seng 3 repair days

(RED \$2447.68; 64%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 27/9 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) ___ S + RS ___ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : TP

Lump Sum / +B: (\$ 1500)

TOTAL

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Email: reliablecarzpl@gmail.com

Vehicle No.: SLM 9336 L

Model: HONDA FIT

REF: RC3313

QTY DESCRIPTION

AMOUNT (\$S)

List Items:

1	Front door LH	833.50	X
1	Front door black tape LH	25.80	✓
1	Rear door LH	799.50	✓
1	Rear door black tape LH	25.40	✓
2	Rear door hinge tape LH @ S\$45.20	90.40	X
1	Rear door glass outer moulding LH	42.70	X
1	Rear door regulator LH	290.40	X
1	Rear door outer handle LH	149.20	X
1	Front side mirror LH	280.40	✓
1	Front side mirror cover LH	47.30	✓
1	Rear fender LH		
		REPAIR	X
		2584.60	
Less 20 %		(516.92)	
Subtotal		2067.68	

Labour Charges:

To transfer front door mechanism	11	180.00	X
To transfer rear door mechanism		180.00	50
To check wiring system		120.00	20
To panel beating		500.00	200
To spray painting on affected areas		800.00	680
Subtotal		1780.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$S 3,847.68

Not Authorised
 25/8/21
 2/5 = 1500/
 3 days
 when the After repair

LKKA Auto Consultants hereby notify the Repairer of the following:

- To resurvey before water spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

1 of 1