

PKS AUTOMOTIVE PTE LTD

7 Toh Guan Road East, Alpha Industrial Building #04-11 Singapore 608599

Tel : 6514 6767 / 9182 6686 | Email : admin@pkssautomotive.com

INDIAN INTERNATIONAL INSURANCE PRIVATE LIMITED

VEHICLE NO : SLU56431
MAKE MODEL : MERCEDES/GLA180
REFERENCE : PKS-202102-16
DOA : 13-Feb-21
CLAIM TYPE : Third Party Claim

ATTN: MOTOR CLAIMS DEPARTMENT

Page 1 of 2

FRONT BUMPER	1	\$ 1,898.00	\$ 1,898.00	1,345
FRONT BUMPER SIDE RETAINER LH	1	\$ 127.00	\$ 127.00	
FRONT BUMPER SIDE RETAINER RH	1	\$ 127.00	\$ 127.00	
FRONT GRILLE LH	1	\$ 301.00	\$ 301.00	
FRONT BUMPER NOZZLE COVER LH	1	\$ 112.00	\$ 112.00	
FRONT BUMPER SENSOR LH	2	\$ 642.00	\$ 642.00	376
FRONT FENDER LH	1	\$ 997.00	\$ 997.00	
FRONT FENDER INNER SHIELD LH	1	\$ 254.00	\$ 254.00	
FRONT FENDER LOWER GARNISH LH	1	\$ 550.00	\$ 550.00	108
FRONT HEADLAMP LH	1	\$ 5,458.00	\$ 5,458.00	2,581
FRONT HEADLAMP BRACKET LH	1	\$ 159.00	\$ 159.00	
FRONT DOOR PANEL LH	1	\$ 1,794.00	\$ 1,794.00	
FRONT DOOR HINGE LH	2	\$ 214.00	\$ 214.00	
FRONT DOOR WEATHERSTRIP LH	1	\$ 374.00	\$ 374.00	
FRONT DOOR LOCK ASSY LH	1	\$ 483.00	\$ 483.00	
FRONT DOOR BEARING BRACKET LH	1	\$ 160.00	\$ 160.00	
FRONT DOOR REGULATOR MOTOR LH	1	\$ 540.00	\$ 540.00	
FRONT DOOR INNER TRIM LH	1	\$ 954.00	\$ 954.00	
FRONT DOOR MIRROR ASSY	1	\$ 1,154.00	\$ 1,154.00	
REAR DOOR PANEL LH	1	\$ 1,742.00	\$ 1,742.00	
REAR DOOR HINGE LH	2	\$ 132.00	\$ 132.00	
REAR DOOR WEATHERSTRIP LH	1	\$ 374.00	\$ 374.00	
SILL GARNISH LH	1	\$ 1,201.00	\$ 1,201.00	745
FRONT STEERING RACK AND PINION	1	\$ 5,673.00	\$ 5,673.00	5,430
STEERING RACK CONTROL UNIT	1	\$ 1,620.00	\$ 1,620.00	
FRONT KNUCKEL ARM LH	1	\$ 886.00	\$ 886.00	
FRONT WHEEL HUB AND BEARING LH	1	\$ 460.00	\$ 460.00	
FRONT SHOCK ABSORBER	1	\$ 772.00	\$ 772.00	
FRONT LOWER ARM LH (FRONT)	1	\$ 774.00	\$ 774.00	
FRONT LOWER ARM LH (REAR)	1	\$ 696.00	\$ 696.00	
FRONT UPPER ARM LH	1	\$ 699.00	\$ 699.00	
FRONT STABILIZER LINKAGE LH	1	\$ 168.00	\$ 168.00	
FRONT LINK ROD LH	1	\$ 68.00	\$ 68.00	
FRONT DRIVESHAFT LH	1	\$ 1,905.00	\$ 1,905.00	
TURNING ANGLE PICK SENSOR	1	\$ 861.00	\$ 861.00	

\$ 34,329.00 19,445
LESS 10 % \$ 3,432.90 -1040
SUBTOTAL \$ 30,896.10 17,995.20
BALANCE C/F \$ 30,896.10

BALANCE B/F \$ 30,896.10				
FRONT BUMPER CLIP	✓ NPL	1 SET	\$ 40.00	\$ 40.00
FRONT FENDER INNER SHIELD CLIP	✓ NPL	1 SET	\$ 30.00	\$ 30.00
FRONT DOOR INNER TRIM CLIP	✓ NPL	1 SET	\$ 30.00	\$ 30.00
RIM	✓ CMC	1	\$ 1,200.00	\$ 1,200.00
TYRE	✓ BSA - 70%	1	\$ 350.00	\$ 350.00
BRAKE FULID	✓ NPL	1 BOT	\$ 60.00	\$ 60.00
SUBTOTAL			\$ 1,710.00	
BALANCE C/F			\$ 32,606.10	1,305

BALANCE B/F \$ 32,606.10				
CHECK FRONT WIRING AND LIGHTING SYSTEM			\$ 80.00	\$ 80.00
REMOVE AND RENEW FRONT SENSOR			\$ 120.00	\$ 120.00
DIAGNOIS CHECK AND CLEAR FAULT CODE			\$ 400.00	\$ 400.00
COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT			\$ 180.00	\$ 180.00
REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS			\$ 300.00	\$ 300.00
REMOVE, RENEW STEERING RACK AND PINION			\$ 250.00	\$ 250.00
TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO NEW			\$ 200.00	\$ 200.00
TRANSFER PARTS, ATTACHMENT FROM OLD REAR DOOR TO NEW			\$ 200.00	\$ 200.00
PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	Repair pillar		\$ 1,400.00	\$ 1,400.00
SPRAY PAINTING ON AFFECTED AREAS			\$ 1,600.00	\$ 1,600.00
APPLY ANTI RUST ON AFFECTED AREAS			\$ 120.00	\$ 120.00
SUBTOTAL			\$ 4,850.00	
GRAND TOTAL			\$ 37,456.10	2,920

Repair day - 8 days

L/S. After paint phew

Sun Pin (Hk)

19/02/2021

TP without prejudice

17,995.50

1,305

2,920

22,220.50

- 20%

17,776.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

L/S

\$17,750

8 days