

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM21D204669/C01/TOHHS Date: 29<sup>th</sup> Oct 2021

Our Ref : CS/CTI21008926/Eqce2

## M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SCA 16P ACCIDENT ON 23/08/2021

Instruction was received to inspect the vehicle Reg. No. SCA 16P. The inspection was conducted on 25/08/2021 at the premises of M/s Blk K Pandan Loop Ind Estate, Pandan Loop, #01-12, Repairer: Goldbell Engineering Pte Ltd.

The following vehicle information was recorded:

Registration Number : SCA 16P

Make/Model : Nissan Sylphy 1.6 CVT

Year of Registration : 2017 Body Colour : White

Chassis Number : MNTBBAB17Z0030026

Engine Capacity : 1598 cc Speedometer Reading : 100972 km

The vehicle sustained damages at the front, rear portion and undercarriage. The Estimated repair cost of such vehicle is S\$19,664.85 (Sin Dollars: Nineteen Thousand Six Hundred Sixty-Four and Eighty-Five Cents only.) (Exclude check items S\$7,100.80Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a)	If the vehicle to be "Total Loss"

Market Value

S\$ 57,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 38,338.00)

S\$ 18,662.00

Less: Excess

(S\$ 1,300.00)

Nett Liability S\$ 17,362.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

19,664.85

(Exclude check items S\$7,100.80Nett)

(S\$ 1,300.00)

Less:Excess

Nett Liability

18,364.85 S\$

(a) - (b) =

**(S**\$ 1,002.85)

The amount of estimated saving of S\$1,002.85 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

CHEN TSUE YEE Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA), AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.