

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305484006

Date 27/08/21

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : Mr THEVAN

Vehicle Reg No. SH 8505R

Date of Accident : 23/08/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBF3591K

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**\$2,800.00**

**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 27/8/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SH 8505R

MAKE TOYOTA

MODEL PRIUS

DATE: 23. August 2021

MVA JUMANI

DOA: 23. Aug. 2021

NTUC

(US)  
(LKK)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$458.60 / Cut
10	REAR BUMPER CLIPS			\$22.00 / nec
1	REAR FENDER LH			\$836.70 / Cut Buc
1	TAILLAMP ASSY UPPER LH			\$557.80 / Cut CRA
1	TAILLAMP ASSY LOWER LH			\$548.40 / Cut
1	REAR BUMPER LOWER COVER			\$552.60 / Xr
1	REAR BUMPER BRACKET LH			\$94.80 / nec
1	SEAL REAR BUMPER SIDE LH			\$148.40 / Cut
1	REAR BUMPER UNDER LH			\$232.00 / Cut
1	REAR BUMPER FLOOR COVER			\$220.50 / Xr
SUB TOTAL				\$3,671.80
LESS 25%				\$917.95
DISCOUNTED TOTAL				\$2,753.85
ADVERTISEMENT LOGO – BUMPER				\$50.00 NET / NEC
ADVERTISEMENT LOGO – FENDER				\$200.00 NET / NEC
				\$250.00
Labour Charge				
PANEL BEATING				\$1,200.00 700
SPRAY PAINT				\$600.00 500
CHECK WIRING				\$50.00 20
TUFF KOTE				\$50.00 20
TOWING FEE				\$60.00 /
REMOVE/REFIX REVERSE SENSOR				\$80.00 30
TOTAL LABOUR				\$2,040.00
ESTIMATE TOTAL				\$5,043.85
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

## INSURER ENQUIRY

Find  
insurer

Vehicle reg. no.

FBF3591K

Date of Accident

23/08/2021 

Reset

## % RESULT &amp; RECEIPT

## TP Insurer Enquiry

Insurance ..... NTUC Income Insurance Co-op...

Period of Insurance ..... 21/06/2021 - 20/06/2022

Requested By ..... Por Moy Juan (COMFORTDELG...

Requested Date ..... 23/08/2021 16:13

## Payment details

Request Amount: S\$1.87


GST Amount: S\$0.13

Total Amount Due (GST Inclusive): S\$2

## General Insurance Association

Records Management Centre

GST Registration No: M400017735

Thuvan Lkh 24/8/21 ~~1500~~ 1500

3clays wp

82235769 thuvan@Lkh auto.lom

L/S after repair photo

SH 1505R

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: