

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008937/GES3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLD8851U	Insured Vehicle No :	SLS8209X
Date of Loss:	22/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003598

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8851U	Engine No:	27492030520275
Make & Model:	MERCEDES-BENZ GLA250, 2.0 4MATIC (A)	Chassis No:	WDC2539462F015295
Reg. Date:	30/06/2016 (Man. Year: 2015)	Odometer:	78684 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,203.70	4,106.90	2,096.80	33.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,200.00	260.00	17.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,663.70	5,306.90	2,356.80	30.75
+ GST 7.00/7.00% (S\$)	536.46	371.48	164.98	30.75
Nett Amount (S\$)	8,200.16	5,678.38	2,521.78	30.75
+ Car Rental (7.0 x S\$160.00/day) (S\$)		1,120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,805.83		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment:	25/08/2021	
Date Inspected:	25/08/2021	Inspected At: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2021)**Parts:** M1-SUV MERCEDES-BENZ GLA250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLD8851U)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILLAMP	Cut	483.00 FL	*483.00 FL
2	1		*REAR BUMPER	Torn	769.00 FL	*769.00 FL
3	1		*REAR BUMPER LOWER PAD	Cracked	445.00 FL	*445.00 FL
4	1		*REAR BUMPER LH REFLECTOR	Cut	29.00 FL	*29.00 FL
5	1		*REAR BUMPER LH OUTER PARKING SENSOR	Damaged	162.00 FL	*162.00 FL
6	1		*REAR BUMPER LH PARKING SENSOR	Damaged	162.00 FL	*162.00 FL
7	1		*REAR BUMPER LOWER CHROME	Cut	407.00 FL	*407.00 FL
8	1		*REAR BUMPER LH SIDE RETAINER	Deformed	122.00 FL	*122.00 FL
9	1		*REAR BUMPER SPONGE	Not Necessary	145.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Buckled	650.00 FL	*650.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	70.00 FL	*70.00 FL
12	1		*REAR LH EXHAUST SILENCER	Repair	2,033.00 FL	*- FL
13	1		*REAR LH EXHAUST SILENCER CHROME	Cut	361.00 FL	*361.00 FL
14	1		*REAR LH EXHAUST SILENCER HEAT SHIELD	Damaged	336.60 FS	*200.00 FS
15	1		*REAR LH WHEEL ARCH GARNISH	Broken	198.00 FL	*198.00 FL
16	1		*REAR LH BOOTLID REFLECTOR	Cut	483.00 FL	*483.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,855.60	4,541.00
- List Item Discount on L Items 10.00/10.00% (S\$)	651.90	434.10
Total Parts (S\$)	6,203.70	4,106.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR DAMAGES	New	580.00	500.00
2	TO SPRAY PAINTING	New	880.00	700.00
			Gross Labour Cost (S\$)	1,460.00
				1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >