



AUTOMOTIVE GROUP

A Sin Ming Autocity, 160 Sin Ming Drive #03-03 Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/082021/4950
Accident date: 22/8/2021
Your Ref : SLS8209X

Tax Invoice:

Date: 24/8/2021

MOTOR CLAIM DEPARTMENT
INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04-#05 IOB Building
Singapore 049711

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Handwritten notes:
C/Ways
P/P
before part price
Caro Qian
25/8/21

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SLD8851U
Model : Mercedes Benz / GLC250

Table with 3 columns: Description, Price, Total. Includes items like Rear LH taillamp, Rear bumper, Rear bumper lower pad, etc. Total repair cost: \$7,663.70.

VIN'S MOTOR PTE LTD

Handwritten signature and line