

Company Reg. No. :201838521G
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
E-mail:xinhuaworkshop2@gmail.com

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNA1343H**
MODEL : **HONDA SHUTTLE**
DATE OF ACCIDENT : 23.08.2021
TIME OF ACCIDENT : 13:30 HRS

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,267.80	\$ 1,267.80
2	FRONT DOOR OUTER HANDLE RH <i>2</i>	1	\$ 386.20	\$ 386.20
3	FRONT DOOR HINGE RH	2	\$ 49.80	\$ 99.60
4	FRONT DOOR CHECKER RH <i>not in</i>	1	\$ 106.40	\$ 106.40
5	FRONT DOOR GLASS CHANNEL RH	1	\$ 84.30	\$ 84.30
6	FRONT DOOR GLASS FRAME BLACK STICKER RH <i>2</i>	2	\$ 98.90	\$ 197.80
7	FRONT DOOR GLASS RH <i>2</i>	1	\$ 468.70	\$ 468.70
8	FRONT DOOR WEATHER STRIP RH <i>2</i>	1	\$ 89.40	\$ 89.40
9	FRONT DOOR INNER LOCK RH <i>1</i>	1	\$ 297.50	\$ 297.50
10	FRONT DOOR FRAME WEATHER STRIP RH	1	\$ 167.40	\$ 167.40
11	FRONT DOOR OUTER STRIP RH <i>1</i>	1	\$ 96.70	\$ 96.70
12	FRONT DOOR LOCK CATCH RH <i>1</i>	1	\$ 20.10	\$ 20.10
13	FRONT DOOR INNER TRIM BOARD RH	1	\$ 649.80	\$ 649.80
14	FRONT DOOR REGULATOR RH	1	\$ 353.50	\$ 353.50
15	FRONT DOOR POWER WINDOW MOTOR RH <i>2</i>	1	\$ 459.60	\$ 459.60
16	FRONT DOOR OUTER KEY LOCK RH	1	\$ 168.70	\$ 168.70
17	FRONT DOOR SPEAKER RH <i>1</i>	1	\$ 197.60	\$ 197.60
18	FRONT DOOR STOPPER RH <i>2</i>	2	\$ 18.90	\$ 37.80
19	REAR DOOR RH <i>Regis</i>	1	\$ 986.70	\$ 986.70
20	REAR DOOR GLASS CHANNEL RH <i>2</i>	1	\$ 82.40	\$ 82.40
21	REAR DOOR POWER WINDOW MOTOR RH	1	\$ 598.70	\$ 598.70
22	REAR DOOR FRAME WEATHERSTRIP RH	1	\$ 176.40	\$ 176.40
23	REAR DOOR INNER LOCK RH <i>1</i>	1	\$ 264.70	\$ 264.70
24	REAR DOOR INNER TRIM RH <i>1</i>	1	\$ 765.80	\$ 765.80
25	REAR DOOR WEATHERSTRIP RH <i>1</i>	1	\$ 184.80	\$ 184.80
26	REAR DOOR OUTER MOULDING RH	1	\$ 127.10	\$ 127.10
27	REAR DOOR GLASS SIDE GARNISH RH	1	\$ 98.70	\$ 98.70
28	REAR DOOR HINGE RH <i>2</i>	2	\$ 49.80	\$ 99.60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNA1343H**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 23.08.2021
 TIME OF ACCIDENT : 13:30 HRS

29	REAR DOOR CHECKER RH	1	\$ 106.40	\$ 106.40	+
30	REAR DOOR FRONT WEATHER STRIP RH	1	\$ 158.60	\$ 158.60	+
31	REAR DOOR LOCK CATCH RH	1	\$ 20.10	\$ 20.10	+
32	REAR DOOR SPEAKER RH	1	\$ 197.60	\$ 197.60	+
33	REAR DOOR GLASS REGULATOR GEAR RH	1	\$ 353.10	\$ 353.10	+
34	REAR DOOR GLASS RH	1	\$ 459.30	\$ 459.30	+
35	REAR DOOR OUTER HANDLE RH	1	\$ 351.20	\$ 351.20	+

1267.8
 1014.24

TOTAL PRICE \$ 10,180.10
 LESS 20% \$ 2,036.02
SUB TOTAL PRICE \$ 8,144.08

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00	+
2	FRONT DOOR TRIM BOARD CLIP (SET)	1	\$ 80.00	\$ 80.00	+
3	FRONT DOOR GLASS SOLAR FILM RH	1	\$ 250.00	\$ 250.00	+
4	REAR DOOR INNER TRIM BOARD CLIP (SET)	1	\$ 80.00	\$ 80.00	+
5	REAR DOOR GLASS SOLAR FILM RH	1	\$ 250.00	\$ 250.00	+

TOTAL \$ 740.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,000.00	200
2	TO SPRAY PAINT	\$ 1,000.00	400
3	TUFF COAT	\$ 250.00	+
4	WIRING, BULB CHECKING	\$ 80.00	+
8	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	✓
9	REMOVE & REFIX FRONT DOOR AUDIO SPEAKER	\$ 120.00	+
11	FOUR WHEEL ALIGNMENT	\$ 120.00	+
13	TRANSFER REAR DOOR MECHANISM	\$ 80.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNA1343H**
MODEL : **HONDA SHUTTLE**
DATE OF ACCIDENT : 23.08.2021
TIME OF ACCIDENT : 13:30 HRS

16	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x

680

TOTAL \$ 3,110.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,884.08
TOTAL LABOUR COST : \$ 3,110.00
TOTAL REPAIR COST : \$ 11,994.08

Adrian Cj
L/S 02/09/21.
03 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

total: 1744.24.
L/S: 1.3k.

IRENE

SERVICE ADVISOR
IRENE
HP : 9151 6861

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: