



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2202890

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 19/05/2022
Reference CC4/LPC21008944/Rea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLA 4684C
Insured Veh. SLP 8242P
Claim No. 21/21/21/VP05/024878
Policy No. Z21VP05029399
Accident Date 24/08/2021
Inspection Date 27/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21008944/Rea3q2 Date: 19/05/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 8242P	Veh. Inspected	SLA 4684C	
Policy No.	Z21VP05029399	Coverage (\$)	0.00	
Claim No.	21/21/21/VP05/024878	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	25/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER PREMIUM 2.0	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600071242	Colour	WHITE	
Odometer	89326 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R19	MICHELIN	6 mm	
L/H Front Tyre	235/50 R19	MICHELIN	6 mm	
R/H Rear Tyre	235/50 R19	MICHELIN	6 mm	
L/H Rear Tyre	235/50 R19	MICHELIN	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	24/08/2021	Inspection Date	27/08/2021	
Survey held at	281 ALEXANDRA RD			
Repairer	PREMIUM AUTOMOBILES PTE LTD			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 4684C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	DEFORMED	1,500.00	1,500.00
1	REAR BUMPER SPOILER (SN)	SCRATCHED	450.00	450.00
2	REAR BUMPER LIGHT REFLECTOR LH/RH (SN)	NOT NECESSARY	150.00	-
2	REAR BUMPER RETAINER LH/RH (SN)	NOT NECESSARY	300.00	-
15	REAR BUMPER CLIPS (SN)	NECESSARY	67.50	67.50
1	REAR BUMPER INNER SPONGE (SN)	NOT NECESSARY	195.00	-
1	REAR BOOT LID (SN)	TO REPAIR SEE LABOUR	2,100.00	-
2	REAR LID SIDE TRIM LH/RH (SN)	NOT NECESSARY	240.00	-
1	REAR LID INNER BOARD LOWER (SN)	NOT NECESSARY	660.00	-
1	REAR LID LOCK (SN)	NOT NECESSARY	900.00	-
1	REAR LID LOCK COVER (SN)	NOT NECESSARY	75.00	-
1	REAR LID LOCK PUSH BUTTON (SN)	NOT NECESSARY	210.00	-
1	REAR LID LOCK STRIKER (SN)	NOT NECESSARY	135.00	-
2	REAR WINDSCREEN MOULDING LH/RH (SN)	NOT NECESSARY	210.00	-
1	REAR WINDSCREEN MOULDING LOWER (SN)	NOT NECESSARY	150.00	-
1	REAR LID EMBLEM 'HARRIER' (SN)	NECESSARY	150.00	150.00
1	REAR LID EMBLEM 'TOYOTA' (SN)	NOT NECESSARY	135.00	-
1	REAR LID GARNISH OUTER (SN)	NOT NECESSARY	1,290.00	-
2	TAILLIGHT INNER LH/RH (SN)	NOT NECESSARY	480.00	-
2	TAILLIGHT OUTER LH/RH(SN)	NOT NECESSARY	1,200.00	-
1	REAR END PANEL UPPER TRIM (SN)	NOT NECESSARY	540.00	-
1	REAR SENSOR (SN)	NOT WORKING	400.00	400.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	200.00	-
1	REAR NO PLATE (SN)	NOT NECESSARY	60.00	-
1	SUNDRIES (SN)	NECESSARY	250.00	30.00
			12,047.50	2,597.50
	<u>LABOUR</u>			
	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR KICK SENSOR .CHECK FUNCTION.		360.00	360.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM ,WIRE HARNESS FOR TAILLIGHTS AND REAR WIPER ASSY .	NOT NECESSARY	480.00	-
	TO RENEW REAR WINDSCREEN.	NOT NECESSARY	480.00	-
	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	NOT NECESSARY	400.00	-
	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	NOT NECESSARY	200.00	-
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		2,400.00	500.00
	TO RESPRAY REAR BUMPER AND REAR LID.		2,400.00	1,000.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			6,912.00	2,052.00
GRAND TOTAL			18,959.50	4,649.50

RECOMMENDED COST OF REPAIRS				4,649.50
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/LPC21008944/Rea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 4684C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 4684C

RE-INSPECTION

