

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/692/2021/GW
DATE : 26-Aug-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 27/8/2021
YOUR INSURED VEH NO : SLP 8242 P

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702
Attn: Motor Claims Dept
Tel: 6827 27692 - Fax: 6225 7402

OWNER'S NAME : MR PHANG CHEE MENG
ADDRESS : BLK 53 HAVE LOCK RD
#16-16
SINGAPORE 161053
TELEPHONE : HP +65 84685068
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10043688R03
VEHICLE NO : SLA 4684 C
MODEL CODE : TOYOTA HARRIER 2.0 CVT
MODEL YEAR : 1/3/2016
ENGINE NO : 3ZRB720438
CHASSIS NO : ZSU600071242
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Aug-21
PLACE OF ACCIDENT : THE U - TURN OF NAN YANG
GIRL'S HIGH SCHOOL TOWARDS
DUNEARN ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 4684 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	/
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	X
3	TO RENEW REAR WINDSCREEN.	S/N \$	480.00	X
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	X
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	500
TOTAL LABOUR CHARGES		:	\$ 4,320.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 4684 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 2,400.00	low
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 6,912.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 4684 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>de -</i>	1	\$ 1,500.00	
2	REAR BUMPER SPOILER <i>an -</i>	1	\$ 450.00	
3	REAR BUMPER LIGHT REFLECTOR LH/RH <i>X</i>	2	\$ 150.00	
4	REAR BUMPER RETAINER <i>CH - X</i>	<i>11/12</i>	\$ 300.00	
5	REAR BUMPER CLIPS <i>re -</i>	15	\$ 67.50	
6	REAR BUMPER INNER SPONGE <i>?</i>	1	\$ 195.00	
7	REAR BOOT LID <i>reput</i>	1	\$ 2,100.00	
8	REAR LID SIDE TRIM LH / RH <i>X</i>	2	\$ 240.00	
9	REAR LID INNER BOARD LOWER <i>X</i>	1	\$ 660.00	
10	REAR LID LOCK <i>X</i>	1	\$ 900.00	
11	REAR LID LOCK COVER <i>X</i>	1	\$ 75.00	
12	REAR LID LOCK PUSH BUTTON <i>X</i>	1	\$ 210.00	
13	REAR LID LOCK STRIKER <i>X</i>	1	\$ 135.00	
14	REAR WINDSCREEN MOULDING LH / RH <i>X</i>	2	\$ 210.00	
15	REAR WINDSCREEN MOULDING LOWER <i>X</i>	1	\$ 150.00	
16	REAR LID EMBLEM 'HARRIER' <i>re -</i>	1	\$ 150.00	
17	REAR LID EMBLEM 'TOYOTA' <i>X</i>	1	\$ 135.00	
18	REAR LID GARNISH OUTER <i>X</i>	1	\$ 1,290.00	
19	TAILLIGHT INNER LH / RH <i>X</i>	2	\$ 480.00	
20	TAILLIGHT OUTER LH / RH <i>X</i>	2	\$ 1,200.00	
SUB TOTAL SPARE PARTS		:	\$ 10,597.50	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 4684 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR END PANEL UPPER TRIM X	1	\$ 540.00	
22	REAR SENSOR nm ✓	1pc ✓	TBC	
23	REAR WINDSCREEN SEALANT X	S/N	\$ 200.00	
24	REAR NO. PLATE X	S/N	\$ 60.00	
25	SUNDRIES ?		\$ 250.00	
TOTAL SPARE PARTS		:	\$ 11,647.50	
TOTAL LABOUR CHARGES		:	\$ 6,912.00	
GRAND TOTAL		:	\$ 18,559.50	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Rasul - Hp 90010068*
SURVEYED DATE : *27/08/21 P10W*
AUTHORISED DATE :
EXCESS COST : *4 day / P/P*
LIABILITY :
REMARKS : *Repy before print*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT